

**Schedule XLV-Form No. 134**

*Ward, Mysore (S)*

**R.W.D (w) Jammal**  
DIVISION  
SUB-DIVISION

**MEASUREMENT BOOK**

**M.B. NO. 27 28.**

*110 N. 12728*

*Surat Dosa Panchayat  
Agro - 04 (B.B.Y. 1980-81)*

*212 Tha - Kondapalli road Road to Sonkharpur Road  
Kondapalli, Mysore (S)*

3rd year maintenance work.

41

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Name of work → construction of wall from Thariba kohbara P.W.D. Road to Sonkhopai.					
② Agency → PWD Bhavnagar					
③ Agreement no. → 4 (C10) / 2020-21					
④ Date of work start → 22-06-2020					
⑤ Actual date of comp → 14/07/2021					

Detailed measurement.

① Restoration of walls etc.	
width of wall =	
$8 \times 10.00 \times 1.10 \times 0.30 = 26.40 m^3$	
$2 \times 16.00 \times 1.20 \times 0.30 = 19.20 m^3$	
$2 \times 26.00 \times 0.90 \times 0.30 = 14.04 m^3$	
$4 \times 18.00 \times 1.00 \times 0.90 = 21.60 m^3$	
$6 \times 8.00 \times 1.00 \times 0.30 = 14.40 m^3$	
$4 \times 11.00 \times 1.00 \times 0.30 = 13.20 m^3$	
$4 \times 8.00 \times 0.80 \times 0.30 = 7.68 m^3$	
$6 \times 5.00 \times 1.00 \times 0.30 = 9.00 m^3$	
	$\sum = 117.82 m^3$

② making up beams/shoulder striking excess soil.	
$3 \times 18.00 \times 1.20 = 64.80 m^3$	
$6 \times 12.00 \times 1.10 = 79.20 m^3$	
C-a <u>144.00 m</u>	

Continuation

Abstract of cost

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of road cut with soil and agri side fly - (41) Times					
		117.82 m <sup>3</sup>			
		at 386.17/m <sup>3</sup>			45495=
② Making up board/bedding stripping excess soil and					
		agri side fly - (42) Times			
		580.60 m <sup>2</sup>			
		10001 - 573.75 m <sup>2</sup>			
		at 57.56/m <sup>2</sup>			33025=
③ Repair of big holes					
		filled with 75 mm soil			
		agri side fly - (42) Times			
		3.14 m <sup>2</sup>			
		at 10056.25/m <sup>2</sup>			31577=
④ Pot repair over pot holes -					
		agri side fly - (42) Times			
		41.866 m <sup>2</sup>			
		at 251.95/m <sup>2</sup>			10548=
⑤ Pot repair over bedding surface -					
		agri side fly - (43) Times			
		42.12 m <sup>2</sup>			
		at 263.91/m <sup>2</sup>			11116=
					13176=

Continuation

B.F.H. 1.31.769 = 00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(6) Maintenance of Home pipe culverts					
at nukley - (43) T.M.S					
3.00 mtr.					
C. 1130.67 per s. m. 3392 = 00					
(7) maintenance of road signs.					
at nukley - (43) T.M.S					
0.26 km.					
C. 1077.82 / km. m. 280 = 00					
(8) maintenance of 200m					
at nukley - (43) T.M.S					
0.31 km.s					
C. 628.24 / km. m. 195 = 00					
(9) cutting of branches					
at trees.					
at nukley - (43) T.M.S					
4.00 nos.					
C. 109.74 / nos. m. 439 = 00					
(10) cutting of shrubs					
from boundary.					
at nukley - (43) T.M.S					
1.00 nos.					
C. 6.73 / nos. m. 101 = 00					
(11) Road marking on C.C.					
at Area.					

B. & H. 13616820