

Block Jaynagar Dhauli Tol PMGSY to Mahadablit tol

Schedule XLV Form No. 134.

कार्यपालक अभियन्ता
ग्राहीण कार्य विभाग
कार्य प्रमण्डल, जयनगर

DIVISION

SUB-DIVISION

(SC)
PMGSY (Maintenance)

691

Measurement Book

Anish kumar Tiwari

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	
(1) Main wall of Culvert				
Width 9 m, H = 1.1 m				
		11.1 m		
W.A. 342.63/m ²				38,935
(2) Main wall of Shoulder				
Width 2 m, H = 3.5 m				
		3.5 m		
W.A. 50.38/m ²				43,175
(3) P.C. 25 m, m. R.W.				
Width 1.5 m, H = 3.6 m				
		3.6 m		
W.A. 58.04/m ²				51,299
(4) Patch Repair of Pol				
Width 1 m, H = 3.6 m				
		3.6 m		
W.A. 17.48/m ²				16,514
(5) Patch Repair of B.S. Surface				
Width 1 m, H = 3.6 m				
		3.6 m		
W.A. 108.99/m ²				14,816
(6) Main wall of 11/12 Culverts				
Width 6 m, H = 3.5 m				
		3.5 m		
W.A. 1047.50/m ²				3143
(7) Main wall of 10/12 Culverts				
Width 1 m, H = 3.5 m				
		3.5 m		
W.A. 216.22/m ²				2162

Continuation

Particulars	Details of actual measurement			Contents of area
	No.	L	B	
(8) Mould. Vol. Road. 1/462				
Side it. 8, P. 38 = 1.88 m. long				
@ 8 - 10 10.45 / km - 1 - 1864 =				
(9) Mould. D. K. m. Stones				
Side it. 9, P. 37 = 0.333 km.				
@ 1 - 676.92 / km - 1 - 225 =				
(10) Cutting True Branches				
Side it. 10, P. 38 = 11 m.				
@ 1 - 97.48 / km - 1 - 1672 =				
(11) Cutting of Shards				
Side it. 11, P. 38 = 23 m.				
(12) Trimming of grass Shards				
Side it. 12, P. 38 = 900.00 m.				
@ 1 - 1.99 / m - 1 - 1791				
(13) White washing of Parapet				
Side it. 13, P. 38 = 24.96 m.				
@ 1 - 20.43 / m - 1 - 516 =				
Total 1 - 176449.00				
Less - 10.1 = 17645 =				
Balance - 158804 = 00				
Sam 24 -				

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
Abstract at Cost.					
(1) Restored of Rain Water					
Wid. P.W. N, item 1/17-43					
= 168.58 m ²					
@ 5.347-63/m ² - A -					58603 =
(2) Repair of Shoulders					
Wid. item 2, P-44 = 936.58 m ²					
@ 5.235/m ² - A -					49057 =
(3) Patching Repair of 75mm B.R.					
Wid. item 3, P-44 = 120.92 m ²					
@ 5.381.04/m ² - A -					64746 =
(4) Patching Repair of Potholes					
Wid. item 4, P-44/45					
= 169.92 m ²					
@ 121.48/m ² - A -					20642 =
(5) Patching Repair of S.P. Surface					
Wid. item 5, P-45 = 169.92 m ²					
@ 108.99/m ² - A -					18520 =
(6) Repair of 410 Culverts					
Wid. item 6, P-45 = 0.3 m ²					
@ 1047.50/m ² - A -					3143 =
(7) Repair of 3160 Culverts					
Wid. item 7, P-45 = 0.1 m ²					
@ 2162.27/m ² - A -					2162 =
Continuation					216873 =

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(8) Maind. of Road Sides					
vide it-8, P-45 = 1.850 km					
@ 10/10.45/10.45-1 = 1869 =					
(9) Maind. of 10 m. Sides					
vide it-9, P-45 = 0.414 km					
@ 10/10.45/10.45-1 = 361 =					
(10) Cutting of Tree Sides					
vide it-10, P-45 = 11 Nos					
@ 10/9.75/10.45-1 = 167.2 =					
(11) Cutting of Shrubs					
vide it-11, P-46 = 23 Nos					
@ 10/5.95/10.45-1 = 135 =					
(12) Trimming of grass					
vide it-12, P-46 = 1500.0 ml					
@ 10/1.99/10.45-1 = 2985 =					
(13) White-washing of Parapets					
vide it-13, P-46 = 27.75 ml					
@ 10/20.43/10.45-1 = 567 =					
Total = 223805.00					
Less 10.1 = 1022381 =					
Balance = 201424 = 00					