

# 1st year maintenance

Sch. XLV-Form No. 134

| Particulars                                                                                                      | Details of actual measurement |    |    |    | Contents of area |
|------------------------------------------------------------------------------------------------------------------|-------------------------------|----|----|----|------------------|
|                                                                                                                  | No.                           | L. | B. | D. |                  |
| Name of work:- Maintenance of road from Sadpur Bhesiga Kala road to Nawaia via Mathura Kala for 1st year. (mmgs) |                               |    |    |    |                  |
| Agency:- m/s Siddhanta Construction                                                                              |                               |    |    |    |                  |
| At - Amra; P.S. Mutassil, Gaya.                                                                                  |                               |    |    |    |                  |
| App. No:- SBD/                                                                                                   |                               |    |    |    |                  |
| Date of Commencement:- 06/09/2019                                                                                |                               |    |    |    |                  |
| Date of Completion:- 05/09/2020                                                                                  |                               |    |    |    |                  |
| Date of Entry:-                                                                                                  |                               |    |    |    |                  |

|    |                                            |  |  |  |               |
|----|--------------------------------------------|--|--|--|---------------|
| 1) | Restoration of drain                       |  |  |  |               |
|    | Cuts / berms                               |  |  |  |               |
|    | do                                         |  |  |  |               |
|    | $2 \times 30.00 \times 1.25 \times 0.30 =$ |  |  |  | $22.50 m^3$   |
|    | $1 \times 30.00 \times 1.25 \times 0.30 =$ |  |  |  | $11.25 m^3$   |
|    | $1 \times 2.00 \times 1.25 \times 0.30 =$  |  |  |  | $0.75 m^3$    |
|    |                                            |  |  |  | $= 34.50 m^3$ |
| 2) | making up of berms/                        |  |  |  |               |
|    | Shoulders                                  |  |  |  |               |
|    | do                                         |  |  |  |               |
|    | $2 \times 30.00 \times 1.25 =$             |  |  |  | $75.00 m^2$   |
|    | $3 \times 30.00 \times 1.25 =$             |  |  |  | $112.50 m^2$  |
|    | $1 \times 4.00 \times 1.25 =$              |  |  |  | $5.00 m^2$    |
|    |                                            |  |  |  | $192.50 m^2$  |

Continuation  
Limit -  $191.87 m^2$

| material statement |                                                      |
|--------------------|------------------------------------------------------|
| (1)                | E/W - $34.53 \text{ m}^3$                            |
| (2)                | WBM (Gr-3) - $0.05 \text{ m}^3$                      |
| (3)                | SS-1 - $0.037 \text{ m}^3$                           |
| (4)                | RS-1 - $0.010 \text{ m}^3$                           |
| (5)                | S-90 - $0.061 \text{ m}^3$                           |
| (6)                | Stone chips - $0.86 \text{ m}^3$<br>(13.2 - 0.09 mm) |
| (7)                | Slow curing bitumen emulsion - $0.045 \text{ m}^3$   |

Scanned with CamScanner