

4th year maintenance Bill

66

MMCSY-0200

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W - Melma Bazar sam chain to malhabad					
Agency - Sri Muthuraj Kumar					
Agg. No -					
Date of measure -					
Date of work -					
Date of Entry - 27/8/2024					
1/15.1) Restoration of rain cut					
do do					
4.5 X 5.0m X 1.1m X 0.300m = 74.25m ³					

2/15.2) making up of Beram/shoulder
do do
24 X 14m X 1.2m = 403.20m²

3/15.3(1)) Repair of post hole filled
do do
41 X 1.4m X 1.5m X 0.075m
= 6.45m³

4/15.20(1)) Patch repair over post
holes do do
41 X 1.4m X 1.5m = 86.1me

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
7 15.700) maintenance of C/D slab type - do all QVTMBP (65) = 2 MU @ R 1066.50/each — R 2133.00					
8 15.43) white washing on Parapet — do — all QVTMBP (65) = 63 m ² @ R 16.17/m ² — R 1019.00 153457.00					
9 25/8/20 JE					