

5th year maintenance

65

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: Primary school to Bhongha 70/19/1000 Nadi Pak					
2. Name of Agency: Reckon infra Tech					
3. Agreement No: 135/SBD/2018-19					
4. Actual date of completion: 18-08-2019					
① Restoration of a/c in cuts with 80% new FUR					
	1	20.50	0.70	0.30	4.305
	1	18.20	0.68	0.30	3.712
	1	20.50	0.65	0.28	3.781
	1	30.0	0.60	0.32	5.760
	2	30.60	0.52	0.30	6.427
	1	12.50	0.40	0.30	1.50
	2	18.60	0.52	0.30	5.803
	3	30.60	0.60	0.30	11.124
	1	2.50	0.70	0.30	0.525
					Qty = 42.887 m ³
					Say Qty = 42.83 m ³
② main entrance of earthen & shoulder of road					
	1	20.50	0.70		14.35
	5	18.50	0.70		64.75
	6	20.60	0.65		80.34
	2	30.0	0.60		36.0
	2	30.0	0.62		37.20
	1	10.0	0.60		6.0

Continuation

Qty = 238.64

Say Qty = 237.94 m³



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					BFR 189984 = ∞
Less 1 + 6% Selone 78					22.04 = ∞
					187780 = ∞
<i>Ram</i> 10.07.2029					
J-E					AE

material statement

(i) Earth	—	78.521m ³
(ii) Bitumen 90	—	244.56kg
(iii) Stone chips	—	3.310m ³
<i>Ram</i> 10.07.2029		
J-E		

Continuation