

HEAD: NABARD Form

Schedule XIV-Form No. 134
Ag. No. 20888/17.18

31st Dec - 31st Dec 2018

DIVISION

SUB-DIVISION

M. B. No. 884

Measurement Book → **884**

Actual Date of Completion - 14/6/2019

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5th year maint.					
Name of work:-	S.P. road to				
Tilaknagar talq	via Jamadpur				
Mahadit talq	in Block -				
Dhanduq.					
Name of Contractor -	Sri Rangesht				
	Kumar.				
Agg-No:-	SSB3/20/2017-18				
Actual date of Comp:-	28/04/2018				
Maint. period -	29/4/2022 to 28/4/2023				

Record Measurement

① Restoration of rain cuts -					
5	12.00	1.20	0.30	21.60	
8	10.00	0.90	0.75	13.50	
2	7.00	1.50	0.60	8.40	
6	9.00	0.75	0.45	18.23	
4	11.00	0.90	0.30	11.88	
7	13.00	1.00	0.30	27.30	
2	13.00	1.00	0.30	7.88	
2	10.00	1.00	0.30	12.00	
				120.71	
				127.01	m ³

② Making up loss of material

Sch. XLV-Form No. 134

Handwritten notes on a grid background:

- $C \rightarrow$
- $\frac{1}{2}$
- $29.04.23$