

5 year maintenance.

22

Sch. XLV-Form No. 134

Sch. XLV Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D	
Name of work:- Corb- of					
read from 6042 - to					
Chhotaki Kherui					
under G.T.S.N.Y.					
Agency - Shonu Kumar					
Assao - 13 SBT/2018-19					
D.O.S - 03.11.18					
D.O.C - 02.5.19					
1 15.12	Restoration of rain				
	cuts with soil--				
	--- all cut				
	19 x 2.0 x 0.30 x 0.250 =				2.25m ³
	40 x 2.20 x 0.30 x 0.250 =				6.60
	42 x 1.75 x 0.30 x 0.250 =				6.30
	54 x 1.50 x 0.30 x 0.250 =				6.07
	60 x 1.60 x 0.30 x 0.250 =				7.20
	65 x 1.75 x 0.25 x 0.250 =				7.10
					= 36.12m ³
2 15.12	Main-embankment of				
	Barthen shoulder				
	--- all cut.				
	2 x 4 x 30.0 x 0.50 =				120.0m ²
	10 x 6.0 x 0.30 =				18.0
10 x 10.0 x 0.30 =				30.0	
15 x 6.0 x 0.30 =				28.80	
				= 196.80m ²	

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5th year maintenance					
* ABSTRACT OF COST					
Name of work - Const. of road					
from L42 to Chhetaki					
Khamri					
Under G.T.S.M.Y					
Agency - Shanku Kumar					
H.S.No - 13 SBD/2018-19					
D.O.S - 03.11.2018					
D.O.C - 02.05.2019					
1/15.1) Restoration of					
raincuts with soil					
--- all					
Dty vide p.no - (22) T.M.B.					
36.12 m ² by 347.63/m ² = 12556.0					
2/15.2) Maintenance of					
earthen shoulder					
--- etc all					
Dty vide p.no - (22) T.M.B.					
196.80 m ² by 52.58/m ² = 10348.0					
3/15.3) Maintenance of					
road sign, etc					
Dty vide p.no - (23) T.M.B.					
0.450 km by 1010.45/km = 455.0					
4/15.4) Maintenance of road					
and K.M. stone.					
Dty vide p.no - (23) T.M.B.					
0.120 km by 678.88/km = 81.0					
Continuation					23440.0

Accepted
28/7/22
Executive Engineer
RWD Works Div-Kharagpur, Tarapur