

MMGSY (S.C)

Schedule XLV — Form No. 134

WORK:- L034 to Paschim Kharar

दि 10 गो प्रेस, गया ।

BIHAR P. W. D.

Executive engineer RMD Shezghati DIVISION

A. E. RMD Shezghati SUB DIVISION

Dharamraj Kumar
MEASUREMENT BOOK

1386

1st year maintenance

36

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: - Main, of Road					
from 1034 to 195 chime					
Kharay under elongation					
Block					
Name of Agency: - Dhamjay					
Kumar					
Agreement no: - 43/SB0/2021-22					
(mm 654/50)					
Date of work order: - 30/12/21					
Date of completion: - 29/12/22					
Actual dated completion: - 30/6/23					
Date of measurement: -					

measurements					
(1) restoration of Pathways					
with soil etc - 200					
5x14.20x1.05x0.25=	18.63m ³				
6x12.90x1.10x0.25=	19.801				
4x9.00x1.00x0.30=	10.801				
	49.23m ³				
	47.94m ³				
(2) making up of Berms shoulder					
stripping of excess soil					
6x8.00x1.00=	48.00m ²				
7x12.00x1.00=	84.001				
7x10.30x1.10=	79.311				
5x11.00x1.00=	55.001				
	266.31m ²				

Continuation

Material statements	
1) E work	76.69 m ³
2) Stone aggregates	1.79 m ³
3) Stone dust	0.33 m ³

Scanned with CamScanner

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1st 48cm main.					-
Amount of cost					
(1) Restoration of pavement with soil etc. - 106.					
width - 36 item (1)					
47.94 m ³ Q.B. 404.06 m ³ B.					19371.60
(2) making up of Berms.					
shoulder stripping of excess soil etc. - 106.					
width - 36 item (2)					
266.31 m ² Q.B. 60.28 m ² B.					15053.60
(3) Repair of pot holes					
filled with 15 mm B.M.					
width - 37 item (3)					
0.06 m ³ Q.B. 9398.5 m ³ B.					5642.60
(4) patch repair over 20 mm					
from corner etc. - 106.					
width - 37 item (4)					
21.63 m ² Q.B. 244.51 m ² B.					5289.60
(5) patch repair of 20 mm max					
seal surface etc. - 106.					
width - 37 item (5)					
21.63 m ² Q.B. 261.94 m ² B.					5666.60
					B. 46943.60

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					B.R. Rs. 46943=00
(6) Filling of corners and joining					
width P-37 item (6)					
947.00m CB. 3-85/m Rs. 3646=00					
(7) Repair of Isolated area of damaged concrete pavement					
cont 612-506.					
width P-37 item (7)					
12.00m CB. 244-51/m Rs. 2934=00					
(8) Removal of existing seal and seasoning of construction					
width P-38 item (8)					
482.82m CB. 2443/m Rs. 11650=00					
(9) maint. of C.D. works. H/R/R					
width P-38 item (9)					
7 no CB. 1166.58/m Rs. 8166=00					
(10) maint. of Road sign					
width P-38 item (10)					
1.46 km CB. 1104.59/km Rs. 1613=00					
(11) maint. of room and kitchen					
width P-38 item (11)					
1.46 km CB. 643=17/km Rs. 939=00					
(12) cutting of trees and shrubs					
width P-38 item (12)					
3 no CB. 113.64 Rs. 341=00					
					Rs. 76232=00

Continuation

Continuation