

2nd year maintenance

36

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
NAME of Road:- Bluphilokha					
Path 9889 to Jagatpath					
Rajput tola.					
Agency - Smt - Jayanti Devi					
Date of start 12/02/2020					
Date of completion - 11/02/21					
Actual completion date - 28/2/22					
Record Entry.					
Item ① Restoration of					
Rain cuts with soil--					
4x	4.80	x 0.85	x 0.30	=	4.90 m ³
6x	2.50	x 0.85	x 0.30	=	3.38 m ³
8x	4.10	x 0.85	x 0.30	=	8.36 m ³
2x	5.60	x 0.85	x 0.30	=	2.86 m ³
5x	3.10	x 0.85	x 0.30	=	3.95 m ³
9x	2.80	x 0.85	x 0.30	=	5.28 m ³
7x	4.60	x 0.85	x 0.30	=	8.21 m ³
10	x 1.75	x 0.85	x 0.30	=	4.46 m ³
12	x 1.60	x 0.85	x 0.30	=	4.89 m ³
14	x 1.90	x 0.85	x 0.30	=	6.78 m ³
11	x 2.75	x 0.85	x 0.30	=	7.71 m ³
7x	1.80	x 0.85	x 0.30	=	3.21 m ³
13	x 2.20	x 0.85	x 0.30	=	7.29 m ³
8x	4.50	x 0.85	x 0.30	=	9.18 m ³
Qty =					80.48 m ³
Item ② Maintenance of					
making up of berm/					
that shoulder - - -					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2x8	x 4.50	x 0.85			61.20 m ²
2x6	x 5.10	x 0.85			52.02 m ²
2x4	x 6.80	x 0.85			46.24 m ²
2x8	x 4.90	x 0.85			66.64 m ²
2x5	x 8.10	x 0.85			68.85 m ²
2x3	x 10.30	x 0.85			53.55 m ²
2x7	x 7.80	x 0.85			117.34
					92.82
				Qty = 44	1.32 m
Item (3) Maintenance of					
Bitumen M.S.S. Road					
Repair to pot hole					
6x	2.10	x 1.50			18.90 m ²
4x	1.75	x 1.20			8.24 m ²
7x	1.70	x 0.95			12.64 m ²
8x	1.80	x 0.85			7.65 m ²
8x	1.70	x 0.85			11.56 m ²
2x	2.50	x 0.60			3.00 m ²
				Qty = 6	1.99 m ²
Item (4) Maintenance of					
C/P Work (H.P.C)					
				Qty =	2.00 m ²
Item (5) Maintenance					
of C/P Work (S.P.C)					
C/P Work					
				Qty =	2.00 m ²
Item (6) Maintenance					
of Road Sign					
				Qty = 0.16	kg

39
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of COSA					
Name of Board: - Bhutahi					
Lokhas Path Dax89 to					
Jaganpatti Rajpoot to 19					
Agency - Smt Jaypatti Devi					
Agreement No - SBD / 100 / 2019-20					
Date of start - 12/2/2020					
Completion date - 11/2/2021					
Actual Date comp - 24/2/22					
Measurement Date -					
Item - (1) Restoration					
of Rain cut with Sid -					
vide T.M.B Page (36)					
Qty = 80.26 m ³					
CS = 380.58 / m ² - 30621 =					
Item - (2) Maintenance					
Making up to bever					
Shoulder - - -					
vide T.M.B Page (37)					
Qty = 441.32 m ²					
CS = 58.33 / m ² - 25759 =					
Item - (3) Maintenance of					
Britannia M.S.S Road					
Repair pot-hole - - -					
vide T.M.B Page (38)					
Qty = 61.99 m ²					
CS = 309.34 / m ² - 19207 =					
CS = 75 587 = 0					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		132	132	828	1224
vide T.M. 13 P. 24 - (38)					
Qty = 42.00 m ²					
@ 15 = 16.657 m ² - 699 =					
			132	83	51124
Add 1% L.C. - 132				825 =	
12% 6.57 m ² = 1002124					
			132	9436724	
2515104					
2515104					
12/8/20					
Material					
E/W - 126.55 m ²					
@ 15 = 23.21 m ² - 3000 =					
Stone dusting.					
13.20 m ² to 0.09 m ² .					
Qty = 1.673 m ²					
@ 15 = 479.28 m ² - 802 =					
			132	380225	
Tack Coat Qty = 0.019 m ²					
M.S.S. v. 20 - 0.117 m ²					
2515104					
2515104					

Continuation