

Sch. XLV-Form No. 134					
Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>5th year of maintenance</u>					
Name of Road Belonging to					
Masjid de Rampalli Boring					
TAK. 15 Kolar Block					
Contractor: Rina Kumar					
Agreement No. → MNA GSY/580/92/					
18-19					
Date of Completion -					12/5/19
work done					

① Restoration of road as					
with soft morum gravel					
or a mixture of both					
	2	4.18	1.15	0.30	2.88 m ³
	3	2.28	1.31	0.30	2.68 m ³
	5	3.98	1.28	0.30	27.64 m ³
	6	4.96	1.21	0.30	10.80
	4	5.25	1.16	0.30	27.30 m ³
	5	3.15	1.29	0.30	6.09 m ³
					37.39 m ³
② Making up loss of					
materials irregular on					
Shoulder along all edge					
or					

