

| Particulars | Details of actual measurement |    |    |    | Contents of area |
|-------------|-------------------------------|----|----|----|------------------|
|             | No.                           | L. | B. | D. |                  |

2nd year Maint Bill

Name of Work - Nimali  
chowk to Parca Phangerola  
Sanichari.

Authority - E.E.R.W.D. Bagaha-1

Agency - Sharda Const.

Agg. no - 44 SBD / 2020-21

D/S - 5/12/2020

D/C - 4/12/2021

A/D/C - 30/6/2022

① Restoration of rain cuts  
with soil -

$$44 \times 2.20 \times 1.50 \times 0.30 = 43.56 \text{ m}^3$$

② Maint. of Earthen  
shoulder with soil -

$$41 \times 6.85 \times 1.10 = 308.34 \text{ m}^2$$

③ Patch repair over bituminous  
surface -

$$2.2 \times 1.45 \times 1.20 = 3.828 \text{ m}^2$$

④ Maint. of H.P. Culvert -

$$1 \times 1 \text{ nos} = 1 \text{ nos.}$$

⑤ Maint. of road signs -

$$1 \times 0.52 \text{ km} = 0.52 \text{ km}$$

Continuation

## Sch. XLV-Form No. 134

| Particulars         | Details of actual measurement |    |    |    | Contents of area |
|---------------------|-------------------------------|----|----|----|------------------|
|                     | No.                           | L. | B. | D. |                  |
| B/F Amt =           | 90180                         |    |    |    | = 00             |
| Less 6.26 % Below = | 5645                          |    |    |    | = 00             |
|                     |                               |    |    |    | = 84535 = 00     |

Sum  
29/6/24  
J.E.

~~Meddred  
29/6/24  
J.E.~~

## Material statement

E/W — 75m<sup>3</sup>

chips — 1m<sup>3</sup>

Bitumen — 0.0946MT

Sum  
29/6/24  
J.E.

~~Meddred  
29/6/24  
J.E.~~

Continuation