

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2nd Year Maint. Bill					
Name of work - PMGSY					
Road at Gonauli to					
Mal Tola.					
Authority - E.E. R.W.D.					
Bazaha-1.					
Agency - New Blue					
Star Construction.					
Agg. no - 27 SBD/2021-22					
D/S - 3/7/2021					
D/C - 2/7/2022					
A/D/C - 17/6/2022					

① Restoration of rain cuts with soil -

$$24 \times 2.30 \times 1.20 \times 0.30 = 19.87 \text{ m}^3$$

$$34 \times 2.40 \times 1.56 \times 0.30 = 38.19 \text{ m}^3$$

$$\cancel{8 \times 1.80 \times 1.30 \times 0.30 = 5.62 \text{ m}^3}$$

$$= 58.06 \text{ m}^3$$

$$\text{Limitity} = 57.71 \text{ m}^3$$

② Maint. of earthen

Shoulder with soil -

$$\cancel{38 \times 10.45 \times 1.10 = 436.81 \text{ m}^2}$$

③ Repair of pot holes filled

with 75 mm W.B.M. -

$$15 \times 1.80 \times 1.20 = 35.10 \text{ m}^2$$

$$19 \times 1.50 \times 1.10 = 31.35 \text{ m}^2$$

$$= 66.45 \text{ m}^2$$

$$38 \times 10.45 \times 1.10 = 436.81 \text{ m}^2$$

Continuation

Continuation