

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2nd year Maint. Bill					
Name of Work - PMGSY					
Laxnauta to Chand					
Barwa (Dhobitola).					
Authority - E.E. RWD.					
Bagaha-1					
Agency - Rajesh Kumar					
Singh.					
Agg. no - 43 SBD/2019-20					
D/S - 9/9/2019					
D/C - 8/9/2020.					

① Restoration of rain cuts with soil -

$$40 \times 2.40 \times 1.60 \times 0.30 = 46.08 \text{ m}^3$$

$$36 \times 2.20 \times 1.50 \times 0.30 = 37.26 \text{ m}^3$$

$$= 83.34 \text{ m}^3$$

② Maint. of Earthen shoulder with soil -

$$33 \times 6.70 \times 1.10 = 243.21 \text{ m}^2$$

③ Patch repair over B.T. surface

$$16 \times 1.45 \times 1.15 = 26.68 \text{ m}^2$$

Continuation

Continuation