

2nd year Maining

Sch. XLV-Form No.134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W : Maintenance of Road from 1052 To 0 (Kapsa Tol)					
Under. GTS NY					
Block - Dhang length - 0.500 KM					
Authority - E E RWD(W) Div - Dhang					
Agency - Vishnu Dev Patro.					
1. S.K. Nagar, Motihari					
2. Chambaran.					
Agreement No - 39 SBD / 2018-19					
Actual Date of completion - 31.01.2019					
Maintenance work has been done by Agency & details as per below -					
1. Maintenance of Earthen Shoulder filling					
6 x 8.10 x 0.80 = 38.88					
10 x 8.20 x 0.90 = 72.00					
14 x 9.00 x 0.50 = 14.00					
T 78.00 m ²					
Month May 2020					
1. Maintenance of Earthen Shoulder filling					
6 x 8.10 x 0.80 = 38.88					
10 x 8.20 x 0.90 = 72.00					
14 x 9.00 x 0.50 = 14.00					
T 78.00 m ²					
Month Jun 2020					
1. Rehabilitation of New culi					
width Soil 1.00 x 0.30 = 0.30 x 0.30					
8 x 9.00 x 0.70 x 0.30 = 15.12					
12 x 6.10 x 0.50 x 0.30 = 10.98					

CONTINUATION

Sch. XLV-Form No.134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
1/2 Maintenance of Eddies					
shoulder A.U.J					
78.00 m ²	wide Tm3 P 18				
71.95 m ²	P 19				
149.95 m ²	① 54.37 m ²	b	8153 ~		
2/1 Restoration & Reinforcement					
with soil					
wide Tm3 P 19					
27.00 m ³	① R 365 = 25 / m ³	9	9862 ~		
3/4 Mainslain 200 m & 1m					
Star by way					
wide Tm3 P 19					
0.500 km	① 1 740.27 / km	L	370 ~		
		b	18385 ~		
km 0.03 - below			8 ~		
		b	18349 ~		
Signature					
26/1/2019					
AG					
<u>Masonry Stabilized</u>					
Soil = 27.00 m ³					
LAD F S G GLBGS					
OPEN & CLOSING OF MUDGATE CHANNEL					
COLIBUS					