

MINUSY (Sc)

Schedule XLV-Form No. 134

Const. of road. Musharniya to Charnpura

11/12 01/11/11

DIVISION

Abeto

SUB-DIVISION

Agency - Sant. Jaybati Devi

MEASUREMENT BOOK

11/12 01/11/11

3118

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	Agst	Year maintenance			Work
N/W:- Mughal area to chain up.					
Agency:- Smt Jaypatti Devi					
Agst. No. 10- S.B.D. / 20-21					
Maintenance Period:- 3/01/23 to 2/01/24					
Measure ment					
① Restoration of Raincut					
14 x 5.30	x 0.90	x 0.30			= 20.03 m ³
18 x 4.70	x 0.80	x 0.30			= 20.30 "
18 x 3.80	x 0.90	x 0.30			= 18.47 "
12 x 4.20	x 0.90	x 0.30			= 13.61 "
10 x 3.55	x 0.80	x 0.30			= 8.52 "
					= 80.93 m ³
② Making up Barm / Shoulder					
22 x 5.90	x 1.0				= 129.80 m ²
14 x 4.70	x 0.90				= 59.22 "
16 x 3.60	x 0.80				= 46.08 "
18 x 4.90	x 0.90				= 79.38 "
					= 34.48 m ²
③ Maintenance of Bitumen Road.					
4 x 1.80	x 1.40				= 10.08 m ²
8 x 2.00	x 1.0				= 16.0 "
					= 26.08 m ²
④ Maintenance of H.P. Culvert					
					= 10 NO
⑤ Maintenance of Slab Culvert					
					= 10 NO

Continuation

1) Restoration of Rain cut			
Qty. vide TMB BP-27 = 80.93 m ³			
@ 380.58 per m ³			= R 30800.8
2) Making up for my shoulder			
Qty. vide TMB BP-27 = 315.0 m ²			
@ 58.37 per m ²			= R 18387.0
3) Maintenance of B. I. Hemenau Road			
Qty. vide TMB BP-27 = 26.08 m ⁴			
@ R 33.90 per m ⁴			= R 887.0
4) Maintenance of H. P. Culvert			
Qty. vide TMB BP-27 = 21.9 m ⁰			
@ R 117.0 each			= R 117.0
			= R 58991.0

Continuation

Mathematical Statement 1

9) Earth = 107.9 Sm³

b) Crushed Aggr.	0.70 m ³
------------------	---------------------

2/1/21
epn