

## Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

3<sup>rd</sup> year Maintenance  
From 15.06.2023 to 14.06.2024

Name of work - Maintenance of  
Soil from Bisnupur P. brab.  
PMGSY road to Saituk Lachhu  
Bichla taluk

Agency - M/S Rudra Construction

Agreement No - 50/SBD/2020-21

Agreement Amount - 64.06 + R. 13 & s

Date of Agreement - 15/09/20

Actual date of Completion - 14/06/21

Date of measurement - 14.06.2024

1 Restoration of rain cuts

With soil, stones & gravel

$$1 \times 30 \times 2 \times 0.60 \times 0.30 = 10.80$$

$$1 \times 30 \times 2 \times 0.76 \times 0.30 = 13.68$$

$$2 \times 30 \times 2 \times 0.60 \times 0.30 = 21.60$$

$$1 \times 30 \times 2 \times 0.6 \times 0.30 = 10.80$$

~~10.80~~ ~~10.38~~

~~10.38~~

56.08 m

for 53.87 m<sup>2</sup> 56.08 m

2 Maintenance of

Carton shoulder

by strippling process

Soil from shoulder

## Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
A 13 S TRACT OF Cost					
1 Restoration					
1 Main Cuts with Soil					
Measurement of grossed					
Vide item No. 1 PN-43					
$B_{tr} = 53.87 m^3$					
$@ 386 = 141 m^3 \times 0.801 = 36$					
2 Maintenance					
2 Carthen shoulder					
Stripping excess					
Soil from shoulder					
Vide item No. 2 PN-43					
$B_{tr} = 0.56.50 m^2$					
$@ 57 = 36 m^3 \times 0.80$					
<del>3 Maintenance</del>					
3 Dingsee					
Vide item No. 3 PN-44					
$B_{tr} = 0.111 cm @ 107 = 821 cm \times 118 = 58$					
4 Maintenance of 2cm Stone					
4 K.m Stone					
Vide item No. 4 PN-44					
$B_{tr} = 0.14 cm \times 628 = 261 cm \times 87 = 95$					
$35720.71 \times 0.80 = 28577.6$					
Less 0.25% below w) $\frac{71.14}{71} = 4.5$					
$35649 = 28565.4$					
Say 35640 = 28565.4					
Continuation					
ACW					
1416124					
5.6					