

MMGSY Soso to Prajapati Tola.

GEN

Ag. No:- 06 SBD/20-21 Ag. Val. 30.37406 lak

Schedule XLV-Form No. 134

10% below

Sherghati

DIVISION

Sherghati

SUB-DIVISION

Agency:- Arun Kumar (Vil-Sai Rambigha, Gaya)
Gaya.

MEASUREMENT BOOK

MB no- 1173

3rd year maintenance bill

57

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: -	So. So	to			
	pranapati	to			
Agency: -	Arun Kumar				
Agreement No: -	GS. S. 21	2020			
Date of start: -	8-1	2020			
Date of completion	7-2	2021			
①	Restoration of Rancit				
	Berong de de				
	2 x 418.00 x 1.125 x 0.30				
	x 1.25 =				
	3rd year maintenance = 8.4% = 29.62 m ³				
(2)	making up of				
	Berong/shoulder				
	2 x 418.00 x 1.125 x 1.25 = 1175.625				
	3rd year maintenance				
	14% = 164.58 m ²				

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(3)	Repair of pot hole filled 75mm 100mm dia				
	418.00m	0.15	0.075	1.25	
				X 1.50%	0.089m ²
(4)	patch repair over pot hole 20mm perimeter				
	418.00m	3.75	1.25		1959.325m ²
	3rd year maintenance				
				1.5%	2939m ²
(5)	patch repair over disturbed surface				
	Qty same 4/10 =				29.39m ²
(6)	crack Sealing filling of crack				418.00m
(7)	maintenance of CD HPE -				01 NO
(8)	maintenance of CD slab cur -				01 NO
(9)	maintenance of Road Sign				
	2	418m	0.100		83.60m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(10)	Maintenance of 200m x 100m Singl -				0.418 km
(11)	Cutting of Branch of tree -				3 Nos.
(12)	Cutting of Shrub from roadwing.				418m
(13)	Trimming of grass & weeds -				
	$2 \times 418 \times 1.125 = 940.50 \text{ m}^2$				
(14)	White washing of roadwing				
	$2 \times 21 =$				42.00 ml
	Total 01.07.2024				

Continuation

ABSTRACT COST

3rd year maintenance bill

60

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:-	So	So	to		
pralapati to/a					
Agency:-	Arun Kumar				
Bill:-	Sri ram Bg har				
Agreement No.	06	S.D.	2020-21		
Date of Start:-	8	-5-	2020		
Date of Completion	7	-2-	2021		
(1)	Restoration of Runways				
	de de				
	Qty vide m/s				
	29.62m ³	379.59/m ³	RS	11245=	
(2)	Making up of 20mm				
	Shoulder d				
	Qty vide m/s				
	164.58m ³	56.81/m ³	RS	9350=	
(3)	Repair of pot				
	ho/s d				
	Qty vide m/s				
	0.089m ³	8721.36/m ³	RS	776=	

RS = 21369=00.

Continuation

D.F.R.S. = 21369 = ∞

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(4)	patch repair over				
	pot hole d-de				
	4+4 vide T.M.B. (p) 58				
	29.39 m ² @ 241.64/m ²				
				RS =	7102 = ∞
(5)	patch repair over				
	Bitumen surface				
	4+4 vide T.M.B. (p) 58				
	29.39 m ² @ 247.59/m ²				
				RS =	7277 = ∞
(6)	Crack Sealing				
	4+4 vide T.M.B. (p) 58				
	418.00 m @ 3.63/m			RS =	1517 = ∞
(7)	Maintenance of				
	Road Surface				
	4+4 vide (p) 58				
	01 No @ 1102.81/No RS =				1103 = ∞
(8)	Maintenance of S/b				
	Culvert d-de				
	4+4 vide T.M.B. (p) 58				
	01 No @ 2273.47/No RS =				2273 = ∞
(9)	Maintenance of				
	Road Surface				
	4+4 vide T.M.B. (p) 58				
	83.60 m ² @ 736.00/m ²				
				RS = 61	530 = ∞

to-tal RS = 1,02,171 = ∞
Continuation

[illegible]

Continuation