

1st Year maintenance Bill

20

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ck-11:-		1517	514		
Name of owner:-	1st year				
Maintenance of	stone from				
Dagmotta to Lauriya mustari					
Name of Contractor:-	Prerna				
Devi, w/o:-	Shri vijay				
Yadav,					
Agreement No:-	115 DD/2018-19				
Actual Date of completion:-	15/6/2021				
Date of Entry:-	12/06/2021				
① Restoration of drain cut etc.					
8x 6m					
8x 6m x 0.30m x 0.30m = 4.32m ³					
9x 3m x 0.30m x 0.30m = 2.43m ³					
					6.75m ³
② Maintenance of earthen					
Shoulder etc					
1x 26m x 0.30m = 7.80m ²					
1x 28m x 0.40m = 11.20m ²					
1x 24m x 0.35m = 8.40m ²					
1x 22.50m x 0.45m = 10.12m ²					
					37.52
					m ²

Continuation

C.O.

Continu.

$$\frac{2}{2} \frac{2}{2}$$