

2nd year maintenance

76

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Mending of roof from Chondravu to Bidhanada Border					
Agency - M/s. Om Sai Construction					
Agreement No - 62330/91.22					
Date of start - 10.03.2022					
Actual Completion - 09.03.2022					
Receipt Entry					
(1) Restoration of roing cuts with soil					
—do—					
4 x 6.50 x 0.90 x 0.30 = 7.13					
6 x 3.80 x 0.80 x 0.30 = 5.42					
4 x 3.90 x 0.85 x 0.30 = 3.98					
5 x 4.60 x 0.70 x 0.30 = 4.83					
7 x 3.90 x 0.75 x 0.30 = 6.14					
8 x 3.05 x 0.95 x 0.30 = 6.95					
Total					34.50 m ²
(2) making up berms shoulder exposed soil					
—do—					
2 x 6 x 7.40 x 0.90 = 79.92					
2 x 8 x 5.90 x 0.80 = 75.52					
2 x 9 x 4.60 x 0.95 = 78.61					
Total					234.10 m ²

Continuation

Continuation