

5th year maintenance

43

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
name of work - point of road from mmbly (polder channel) 1/2 to 6/10 to join road 10/9 (Kharung Bk)					
Agency - Sanchi Kharung mmbly					
Agreement no. - 90520/2017-10					
Actual completion - 10.01.2017					
Revised Entry					
1/2 Restoration of road with 10/9 - 10/9					
9 x 6.90 x 0.80 x 0.30 =					14.00
8 x 7.40 x 0.70 x 0.30 =					12.42
7 x 6.70 x 0.85 x 0.30 =					11.96
9 x 6.45 x 1.05 x 0.30 =					12.62
Total =					51.91
2/2 point of earthen channel - 10/9					
2 x 9 x 8.50 x 0.90 =					142.56
2 x 6 x 6.70 x 0.70 =					56.28
2 x 9 x 7.60 x 0.65 =					88.92
Total =					287.76
3/3 Repaired pit					
4 x 3.80 x 0.60 =					8.64
5 x 4.55 x 0.75 =					17.06

Continuation Total 25.20

Continuation