

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1st year Maintenance Bill					
N/W - Const. of Road from					
Bhatuhi Vishali Hanay					
Se. Ghatra Panchayat					
Ke Siman Tak.					
Agency:- Dhananjay Kumar					
Agreement No. - 70 SBD/2019-20					
Date of Work order - 10.7.2019					
Actual date of Completion - 28.03.2023					

①

Restoration of rain

cuts and berms.

$$5 \times 12.1 \times .8 \times .30 = 14.52 \text{ m}^3$$

$$7 \times 9.30 \times .95 \times .30 = 18.55 "$$

$$6 \times 7.8 \times .90 \times .30 = 12.63 "$$

$$6 \times 7.5 \times .90 \times .30 = 12.15 "$$

$$4 \times 10.5 \times .90 \times .30 = 11.34 "$$

$$4 \times 12 \times .90 \times .25 = 10.80 "$$

$$7 \times 6.5 \times .80 \times .30 = 10.92 "$$

$$4 \times 6.5 \times .70 \times .30 = 5.46 "$$

$$\text{C.C. Qty} = 96.803 \text{ m}^3$$

$$\text{Lt.} = 94.92 \text{ m}^3$$

2.

making up berms

and shoulder do 19

$$6 \times 10.5 \times .90 = 56.70 \text{ m}^2$$

Continuation

$$5 \times 9.25 \times .95 = 41.62 "$$

$$8 \times 6.50 \times .90 = 46.80 "$$

$$\text{C.C. Qty} = 145.12 \text{ m}^2$$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF C&U.					
1	Restoration of drain				
Cuts and berms					
94.92 m ²					
@ 380.58/m ²	R				36125.0
2.	making up berms and				
Shoulder. do E19					
385.31 m ²					
@ 58.37/m ²	R				22491.0
3.	Repaired pot hole				
with mss. do E19					
32.11 m ²					
@ 259.71/m ²	R				8339.0
4.	Maintenance of H.P				
Culvert.					
3 Nos					
@ 1117.0/Each	R				3351.0
	C.O.R				70306.00
Let 10% below	(-)				7031.00
	C.O.R				63275.00
By Smt					
26/4/2024					
J.E					
C&P					
30/04/24					