

2nd year maintenance bill

19

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No	L	B	D	

N/W-maintenance Road from
Navadya Pngsy Road se khailan
samudaiak bhawan via malay
asthan matto ke ghar in
makwan block
Agency:- Shubham Construction
Krishnapuri, Bhagolpur,
muzaffarpur.

Agreement NO-132/S30/2019-20

Date of work start:- 03.09.2019

Date of A/c closing:- 02.12.2020

Item:-

1) Restoration of Raincuts/Berms
with do- E12

$$4 \times 8 \times 1.0 \times 0.300 = 9.6 \text{ m}^3$$

$$6 \times 9 \times 0.9 \times 0.300 = 14.58 \text{ m}^3$$

$$5 \times 10 \times 0.95 \times 0.300 = 14.25 \text{ m}^3$$

$$3 \times 12 \times 1.0 \times 0.300 = 10.8 \text{ m}^3$$

$$7 \times 9 \times 0.85 \times 0.300 = 16.065 \text{ m}^3$$

$$8 \times 7 \times 0.90 \times 0.300 = 15.12 \text{ m}^3$$

$$6 \times 8 \times 0.80 \times 0.300 = 11.52 \text{ m}^3$$

$$3 \times 9 \times 0.75 \times 0.300 = 6.075 \text{ m}^3$$

$$9 \times 7 \times 1.0 \times 0.300 = 18.9 \text{ m}^3$$

$$5 \times 10 \times 1.0 \times 0.300 = 15.0 \text{ m}^3$$

$$4 \times 8 \times 0.95 \times 0.300 = 11.52 \text{ m}^3$$

$$3 \times 10 \times 0.90 \times 0.300 = 8.1 \text{ m}^3$$

Continuation

Scanned with CamScanner