

4th year maintenance

54

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: - Tarpaulin Chark to naphor hole line summer Chark - lake					
Spanny - Keshna mountain					
Agg no - 113 / SBD / 2018-19					
Date of start - 20.11.2018					
Date of completion - 19.11.2019					
Actual date of completion - 10.06.2019					
(work done)					
1) Restoration of rain cuts					
2 x 9 x 20 x 0.35 x 0.35 = 66.15 m ³					
3 x 30 x 0.40 x 0.28 = 90 yards					

Q = 116.55 m³

Unit Q = 111.14 m³

2) Maintenance of further shoulder

2 x 10 x 80 x 0.520 = 210 m²

2 x 8 x 28 x 0.450 = 201.60 m²

12 x 3 x 10 x 0.450 = 162 m²

Q = 662.60 m²

3) Maintenance of bitumen m/s rev

5 x 2.75 x 1.60 = 22 m²

10 x 2.90 x 1.50 = 43.50 m²

18 x 2.70 x 1.50 = 72.90 m²

Q = 138.40 m²

4) Maintenance of bitumen surf

5 x 2.75 x 1.60 = 22 m²

Continuation

14276-

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Q = 2 NO @ 2336.82					NO = 4674-
⑥ Maintenance of road right					
City side Tur P (55)					
Q = 2.17 km @ 1087.63					km = 2360-
⑦ Maintenance of road and in 8th					
City side Tur P (55)					
Q = 2.17 km @ 728.56					km = 1581-
					Total = 15081
Less 0.60% below as per aggind (-)					905-
Net amount					148906

4/9/23
26

4/9/23
26

Material Statement

- ① E/W → 111.14 m³ @ 1.71/m³
 ② Stone chips → 7.47 m³ @ 378.28/m³
 ③ Bitumen → 0.663 m³

4/9/23
26

Continuation