

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल दरभंगा-2

Mail ID:-rwdecdbg2@gmail.com

पत्रांक 1956. (अनु०)

दिनांक 25/09/2024

प्रेषक,

ई० अवधेश कुमार,
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्र०, दरभंगा-2

सेवा में,

नोडल पदाधिकारी,
(3054-एम०आर०)
विश्वेश्वरैया भवन, पटना।

विषय:- शीर्ष-3054 (नई अनुरक्षण नीति-2018) अन्तर्गत पूर्ण किये गये पथों में आवंटन मॉग हेतु अधियाचना पत्र समर्पित करने के संबंध में।

महाशय,

उपर्युक्त विषयक के संबंध में गैर योजना मद शीर्ष-3054 (नई अनुरक्षण नीति-2018) अन्तर्गत पूर्ण किये गये पथ में आवंटन मॉग हेतु राशि की अधियाचना विहित प्रपत्र तैयार कर समर्पित की जा रही है।

अतः श्रीमान् से अनुरोध है कि रू० 131.12755 लाख (कुल एक करोड़ एकतीस लाख बारह हजार सात सौ पच्चपन) मात्र रुपये का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु०:- यथोक्त।

विश्वासभाज

कार्यपालक अभियंता,

ग्रामीण कार्य विभाग, कार्य प्र०, दरभंगा-2

24/09/24

FORM GFR 19-A

(See Government of India's Decision (I) below Rule- 150)

Form of Utilisation Certificate up to the month of Sep-2024

Head 3054 Account for M.R (New Maintenance Policy-2018) Yojna. Year 2024-25

PIU Darbhanga-2

Sl. No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Maintenance Account for Head 3054 Account for MR R (New Maintenance Policy- 2018) Yojna	Additional CEO-cum- Secretary Patna, Letter No-94 We Date- 29.08.2024	Rs. 2940.87047	Certified that out of Rs 2940.87047 lacs received during the years 2024-25 in favour of Ex. Engineer RWD work division Darbhanga-2 a sum of Rs 2911.38912 lacs has been utilized for the purpose of Maintenance Account for Head 3054 M.R (New Maintenance Policy-2018) Schemes as given in the margin for which it was sanctioned and that the balance of Rs 29.48135 lacs remaining unutilized at the end of the period under.
	Total		2940.87047	

2. Certified that I have satisfied myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-


- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Constructions materials have tested.
- Measurements have been recorded in the MBs and test check conduction by the Assistant Engineer/ Executive Engineer
- All other codal formalities have been observed.


24/09/24

D. A. O.
R.W.D. Works Division
Darbhanga-2


25/09/24

Executive engineer,
R.W.D. Works Division
Darbhanga-2


24/09/24

ASHISH YADAV
Name of Work/ Road : Raju Chowk Lila Babu tol to Ma
Lab Job number :
Date : 22-09-2024
Section No. 42

Test Date :	22-09-2024	Road Name :	Raju Chowk Lila Babu tol to Ma
Machine No :	477	Road Type :	(R) RURAL ROAD
Start S No :		Side :	
Start E No :		Interval	
Weather :		U/V Range :	1724 To 5000 1000 mm/km
Start Location :		Dist Range :	0 To 1.4 0.1 1000 m
End Location :		Equation :	$Y = 0 * X^2 + 0.827 * X + 574.3$


Print Generate Report and Graph

Redraw Graph

Map View

File : C:\Users\om\Desktop\New folder (7)\Raju Chowk Lila Babu tol to Madhubani Sima Nav tol\18071532.Xls.

Name of Customer : ASHISH YADAV, Name of Work/ Road : Raju Chowk Lila Babu tol to Madhubani Sima Nav tol.



02/09/24
R.V.D (W) Division
Dapthanga-2

NAME OF THE ROAD-Raje Chowk Lila Babu tol to Madhubani Sima Nav tol

NAME OF THE CONTRACTOR - Ashish Yadav

LENGTH-1.260 K.M

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
22/9/24	12:40:15	42	0.1	330	10.1	3300	3303 G		26.234715	86.148799	Normal
22/9/24	12:41:0	42	0.1	300	20.2	3000	3055 G		26.234072	86.148678	Normal
22/9/24	12:41:0	42	0.1	280	20.2	2800	2867 G		26.233449	86.148588	Normal
22/9/24	12:41:32	42	0.1	260	30.3	2600	2724 G		26.234371	86.148704	Normal
22/9/24	12:41:32	42	0.1	290	20.2	2900	3058 G		26.232528	86.148122	Normal
22/9/24	12:42:43	42	0.1	330	0	3300	3303 G		26.231203	86.147	Normal
22/9/24	12:43:0	42	0.1	440	20.2	4400	4213 A		26.23319	86.148368	Speed Bre
22/9/24	12:43:0	42	0.1	270	20.2	2700	3297 A		26.228375	86.146913	Normal
22/9/24	12:43:18	42	0.1	340	20.2	3400	3386 G		26.230339	86.146878	Normal
22/9/24	12:43:18	42	0.1	360	30.3	3600	3269 A		26.227122	86.14703	Normal
22/9/24	12:46:0	42	0.1	370	26.7	3700	3634 G		26.224911	86.14671	Normal
22/9/24	12:48:5	42	0.1	340	20.2	3400	3386 G		26.227665	86.146992	Normal
22/9/24	12:48:11	42	0.1	250	20.2	2500	3671 G		26.224487	86.146755	Normal
AVERAGE IRI							3320.462				

$$Y = 0 * X^2 + 0.827 * X + 574.3$$

$$X = 8200$$

$$Y = 7355$$

(R) RURAL ROAD
Good Average Poor
4001-5000 >5001

Executive Engineer
R.W.D. (W) Division
Darbhanga-2

Done by J.C. 24/09/24
24/09/24
24/09/24

Done by J.C. 24/09/24

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमण्डल दरभंगा-2

प्रमाण-पत्र

विभागीय आदेशानुसार सत्यापित किया जाता है कि शीर्ष 3054 (नई अनुरक्षण नीति-2018) अन्तर्गत Raje Chowk Lila Babu tol to Madhubani Sima Nav tol तक पथ मरम्मत कार्य की जॉच 100 प्रतिशत संबंधित कनीय अभियंता, 50 प्रतिशत संबंधित सहायक अभियंता एवं 10 प्रतिशत कार्यपालक अभियंता द्वारा कर लिया गया है।

Raw
24-09-24
कनीय अभियंता,

paush
24/9/24
सहायक अभियंता

Wad
25/9/24
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग, कार्य प्र0, दरभंगा-2
Paush
24/09/24