

1st year maintenance.

49

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/Work:- Main ⁿ of Road from					
Bachchan Bhagat A					
Gachhi to Mondari					
Siman tak.					
N/Agency:- Buresh Roy.					
Agg. NO:- 042 SBA/2020-21					
D.O.S - 25/06/2020					
A.D.O.C - 25/05/2022					

(Y1)	Restoration of				
	rain cuts-do-eh				
	8x	7.10x	0.80x	0.30	13.44m ³
	7x	9.10x	0.90x	0.30	17.01m ³
	9x	8.10x	0.80x	0.30	17.28m ³
	8x	7.10x	0.90x	0.30	15.12m ³
	7x	9.10x	0.70x	0.30	13.23m ³
				Qty =	76.08m ³

(2/2)	main ⁿ of earthen				
	Shoulder do-do-eh				
	12x	9.10x	0.80	=	86.4m ²
	13x	7.10x	0.50	=	45.50m ²
	14x	8.10x	0.90	=	100.80m ²
	15x	11.10x	0.60	=	99.10m ²
	11x	12.10x	0.80	=	105.60m ²

Continuation

Qty = 437.30m²

52

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B/F	RS=	85782.00
Less 10% below RS(-)					8578.20
				RS=	77204.00