

3rd year maintenance.

Schedule XLV-FORM No. 134

70

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/work:- main ⁿ of Road from Chandeshwar Baltha ke Darwage se Kathaiya mahendra Singh ke Darwage tak					
N/Agency:- Suresh Rai					
A.G.NO:- 178 SBD/2019-20					
D.O.S - 31.12.2019					
A.D.O.C - 2.12.2020					
Date Of Measurement					
(V _i) Restoration of rain cuts - do - do - E/H					
8x 7.60x 0.80x 0.30 = 13.44m					

6x	9.50x	0.00x	0.20x	1.10x
----	-------	-------	-------	-------

@ 14	851.28/m ²	RS =	269515=
(5/4)	main ⁿ of bitumen		
	Surface - do - E/I		
TMB page	(7/5) Qty 82.55m ³		
@ 14	306.19/m ³	RS =	252762=
(6/5)	main ⁿ of Hume pipe		
TMB page	(7/6) Qty 2.10 NO.		
@ 14	1117.10/each	RS =	22342=
(7/6)	main ⁿ of slab type		
	Culvert - do - E/I		
TMB page	(7/7) Qty 6.10 NO.		
@ 14	2309.03/each	RS =	138542=
(8/8)	main ⁿ of 200mm ³ /km		
	Stone - do - E/I		
TMB page	(7/8) Qty 1.58 km.		
@ 14	735.27/km	RS =	11622=
		RS =	391207=
Less below 10%	14(-)		391212=
	Continuation	RS =	352086=


 11/12/23
 JE