

5th year maintenance bill

Heard - Hawans

87

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W - Harrokar to Marhawa village					
N/A - In Ashok Kumar					
Agreement no - 8/BBD/Gen-2018-18					
Date of work - 04.01.2018					
Date of completion - 03.01.2019					
Actual date of completion - 15.12.2018					

Date of receipt: —

1. Restoration of rain cell work

all do 81

30 x 5.50 x 2.00 x 0.452 148.50 m²

25 x 8.50 x 2.00 x 0.452 191.25 m²

18 x 14.50 x 1.50 x 0.300 114.45 m²

Total 454.20 m²

2. Maintenance of earthen boundary to be design and do

2 x 32 m x 30.00 x 1.1252 2160 m²

2 x 2 m x 30.00 x 1.1252 135 m²

1 x 7 m x 30.00 x 1.1252 236.25 m²

1 x 1 m x 12.50 x 1.1252 14.06 m²

Total 2545.31 m²

3. Repair to Pot holes by removal of bitumen/methan

20mm premium Crapch

& steel coat type 2

4 x 16.50 x 1.20 2 79.20 m²

32 x 8.50 x 0.85 2 231.20 m²

25 x 7.50 x 0.65 2 112.12 m²

4 x 23.85 x 1.25 2 119.25 m²

Continuation

Total 541.77 m²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					B.F = 9,72,058 = 00
(e.g. 10% below average)					
Amount = 5m 95206 = 00					
					Net An 8,50,852 = 00
(A). 8,56,852 = 00 as per the bill by					
Six thousand eight hundred and					
two only)					
for					
as per					
J.E.					