

5th Year Maintenance

44

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w = Maintenance of road from					
Horizon To To T069					
Agency = Prabhakar Kumar					
Ag. No. = 69 SBD / 2018 - 19					
Date of Start : 07.03.2019					
Date of Completion : 06.03.2020					
A. Date of completion : 05.03.19					
5 th year Maintenance } 06.08.23 to					
Prime } 05.08.24					
Measurement Record Entry					
D Restoration of drain cuts (m ³)					
1 x 7.15 x 1.20 x 0.30 =					2.57
2 x 8.00 x 1.20 x 0.20 =					3.84
2 x 9.00 x 1.20 x 0.25 =					5.4
1 x 6.10 x 1.20 x 0.30 =					2.19
2 x 8.00 x 1.25 x 0.25 =					5.00
2 x 7.00 x 1.15 x 0.25 =					4.02
2 x 10.00 x 1.25 x 0.30 =					7.5
1 x 6.00 x 1.25 x 0.30 =					2.25
1 x 7.00 x 1.20 x 0.25 =					2.25
4 x 6.10 x 0.90 x 0.25 =					5.49
1 x 18.90 x 1.25 x 0.25 =					5.9
2 x 6.75 x 1.20 x 0.25 =					3.75
1 x 11.30 x 1.25 x 0.20 =					2.82
7 x 2.75 x 1.00 x 0.25 =					4.81
2 x 7.75 x 1.20 x 0.25 =					4.35
5 x 5.50 x 1.15 x 0.25 =					7.90
1 x 24.80 x 1.25 x 0.20 =					6.2

Continuation

= 76.24 m³

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4 x 6.75 x 1.10 =					27.50
3 x 7.15 x 1.20 =					25.74
3 x 4.20 x 1.10 =					13.86
5 x 6.50 x 1.10 =					35.75
5 x 5.50 x 1.20 =					33.00
3 x 5.00 x 1.00 =					15.00
Total =					676.78 m ²
Limit to =					675.00 m ²
③ Maintenance of culvert (H.P) =					2.00 no.

Abstract of cost				
D Restoration of rain cuts				
Q.V.T.M.B P 45 =	12	1.50	m ³	
@ R. 365.25			= R.	44378.00
② Maintenance of earthen shoulder				
Q.V.T.M.B P 46 =	675	.00	m ²	
@ R. 54.37			= R.	36700.00
③ Maintenance of culvert (H.P)				
Q.V.T.M.B P 46 =	02	Nos		
@ R. 1131.64			= R.	2263.00
			= R.	83341.00
less 0.05% below (-)			= R.	42.00
			= R.	83299.00

Continuation