

5th year maintenance.

64

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/Work:- main ⁿ of Road from					
main Road me bholg					
Baitha ke Ghar to					
Kori SC tola tak.					
N/Agency:- Smt. Savitri devi.					
Agg. No:- 49 SBD/2017-18					
D.O.S - 26.08.2017					
D.O.C - 25.08.2018					
A.D.O.C - 09.07.2018					

Date of measurement

(1)

Restoration of rain

cuts - do - do - etc

6x 8.00x 0.70x 0.30 = 10.08m³

5x 9.00x 0.90x 0.30 = 12.15m³

9x 8.00x 0.80x 0.30 = 17.28m³

7x 6.00x 0.90x 0.30 = 11.34m³

5x 20.00x 0.80x 0.30 = 24.00m³

6x 8.00x 1.20x 0.30 = 17.28m³

8x 9.00x 1.30x 0.30 = 28.08m³

Qty = 120.21m³

(2/2)

mainⁿ of eanthen

9x 11.00x 0.60 = 59.40m²

11x 12.00x 0.90 = 118.80m²

12x 13.00x 0.60 = 93.60m²

Continuation

Qty = 271.80m²

[Signature]
14/7/2023
JE

