

1075 To Bahhandiha Tak

Schedule XLV Form No. 134. (M.B.S.Y / W.B)

Bikramganj

BT 0008146

DIVISION

Dinaga

SUB-DIVISION

Measurement Book

NO : 571

# 1st year Maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Repair of Potholes					
	20 mm		M.S.S		
	2 x 2.5 x		1.1 M	= 5.5	
	4 x .90 x		.80 M	= 2.88	
	2 x .80 x		.60 M	= 0.96	
	3 x .70 x		.50 M	= 1.05	
	1 x 1.5 x		1.5 M	= 3.0	
	2 x .50 x		.30 M	= 0.30	
	3 x .40 x		.40 M	= 0.48	
	4 x .30 x		.30 M	= 0.36	
	1 x 4 M x		1.0 M	= 4.0	
	2 x .50 x		.40 M	= 0.40	
	3 x .45 x		.80 M	= 1.08	
	2 x .90 x		.80 M	= 1.44	
	4 x 1.2 x		1.4 M	= 6.72	
	3 x .90 x		.50 M	= 1.35	
	2 x 1.6 x		1.8 M	= 5.76	
	5 x .50 x		.70 M	= 1.75	
	4 x .60 x		.50 M	= 1.20	
	3 x .50 x		.55 M	= 0.82	
	2 x .40 x		.30 M	= 0.24	
	1 x 2 M x		1.1 M	= 2.20	
	2 x 1 M x		1.0 M	= 2.0	
	1 x 3 M x		1.5 M	= 4.5	
	2 x .90 x		.80 M	= 1.44	
	5 x .95 x		.90 M	= 4.27	
	4 x .50 x		.70 M	= 1.40	
	6 x .80 x		.60 M	= 2.88	
	1 x .40 x		.40	= .40	
					58.28

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				BR	25000
Addl	17.	L-C		(+)	250
Addl	12.	GST		(+)	3000
Addl	SF	10% vale			
		Price NO 72 B			820
				Total	29570
L		<del>om</del> 10/7/24 AE		<del>om</del> 10/7/24 JE	

Continuation