

S040 अंश अनुसूची - 0.321 भाग

Schedule XLV-Form No. 134

परिणाम अंश - 64 SBD/2020-2021

MMGSY-6C

अंश

DIVISION

अंश

SUB-DIVISION

अंश

अंश

1224

MEASUREMENT BOOK

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	2nd year maintenance Bill				
Name of work:- Construction of					
road from S40 to					
Titarigand under					
MMGSY (SC)					
Name of Contractor- Mamish					
Singh, A- Anni, Thang-					
muffail, Amani					
Gaya.					
Agreement No.- 64 / S.P. / 2020/2					
Agreement value - 211450/-					
Date of work start - 16/9/2020					
Date of completion - 15/6/2021					
Measurement					
(1) Restoration of road/					
Berms with 2 sides -					
12x 0.90x 0.60x 0.30 = 1.94m ²					
18x 1.20x 0.90x 0.30 = 5.83m ²					
32x 1.00x 0.60x 0.30 = 5.76m ²					
15x 1.30x 1.00x 0.30 = 5.85m ²					
19.38m ²					
2) Making up of berms/					
shoulders, stripping					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
excav. soil from the shoulder					
9x	1.20x	0.90			$= 14.04m^2$
18x	1.60x	1.10			$= 28.80m^2$
26x	2.00x	0.95			$= 49.40m^2$
8x	2.50x	0.80			$= 16.00m^2$
					$108.24m^2$

(3)	Repairs of pot holes filled with Formosa wash				
2x	0.6x	0.60	0.175		$= 0.05m^2$

(4)	Patch repairs over pot holes with Formosa premix carpet				
2x	0.6x	0.6			$= 0.72m^2$
21x	0.90x	0.75			$= 14.17m^2$
					$14.89m^2$

(5)	Patch repair over Bituminous surface with Formosa moseal				
18x	0.75x	0.70			$= 10.12m^2$
14x	0.70x	0.50			$= 4.90m^2$
					$15.02m^2$

(6)	Filling of cracks and joints including				
-----	--	--	--	--	--

Continuation

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	Abstract of cost				
	2nd year Maintenance Bill				
	(All Qty. vide TMB)				
(1/1)	Restoration of Rain				
	Cuts/ Berms with soil				
	Page No. (30) Item No. (1)				
	19.38m ²				
	@ Rs 386.14/m ²				Rs 7483 =
(2/2)	Making up of Berms				
	Shoulder - - -				
	Page No. (31) Item No. (2)				
	108.24m ²				
	@ Rs 57.36/m ²				Rs 6209 =
(3/3)	Repair of Potholes				
	filled with 75mm B.H				
	Page No. (31) Item No. (3)				
	0.65m ³				
	@ Rs 9543.26/m ³				Rs 477 =
(4/4)	Patch repair over				
	Potholes with 50mm				
	Page No. (31) Item No. (4)				
	14.89m ²				
	@ Rs 244.24/m ²				Rs 3637 =

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					0.32 KM @ Rs 628.21/KM Rs 201 =
(10/16)	Cutting of branches of trees				
	Page No. - (32) Item No. (10)				
	2.6 NCM				
					@ Rs 109.74 each Rs 219 =
(11/17)	Cutting of shrubs from road way				
	Page No. - (32)				
	Item No. - (11)				
	321.40 NCM				
					@ Rs 6.73 each Rs 2160 =
(12/18)	Trimming of trees & trees hedges				
	Page No. - (32) Item (12)				
	720 NCM				
					@ Rs 2.24/M Rs 16132
(13/19)	White washing of 19 meter of C/D works				
	Page No. - (33) Item (13)				
	18.80 M ²				
					@ Rs 16.21/M ² Rs 305.60
C.O. - Continuation					Rs 28975 =

Continuation