

2nd year maintenance.

38

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/Work:- main ^m of Road from Bogahi Jarauli Road Kohar to sc to Mushhar to a tak.					
N/Agency:- m/s Devendra Kumar & Company muz.					
Agg NO:- 264 SBD / 2020 - 21					
D.O.S - 15.09.2020					
D.O.C - 14.09.2021					
A.D.O.C - 15.03.2021					
Date of measurement					

(1/1)	Restoration of rain				
	Cuts - do - do - 8/I				
	9x	9.00x	0.60x	0.30 =	14.58 m ³
	8x	8.00x	0.80x	0.30 =	15.36 m ³
	7x	9.00x	0.90x	0.30 =	17.01 m ³
	9x	8.00x	0.80x	0.30 =	17.28 m ³
	8x	7.00x	0.90x	0.30 =	15.12 m ³
				Qty =	79.35 m ³
(2/2)	main of earthen				
	Shoulder - do - do - 8/I				
	9x	8.00x	0.70	=	50.40 m ²
	7x	9.00x	1.30	=	81.90 m ²
	8x	7.00x	0.90	=	50.40 m ²
	9x	8.00x	0.80	=	57.60 m ²

Continuation Qty: 240.30m²

Scanned with CamScanner