

Sch. XLV-Form No. 134

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	

3000 year Maintenance
 N/W - maintenance of H.L.B.
 across Balas River at
 Bhuvanpatti Plot in Dalsingh
 - Sarai Block under NARADA
 Agency - Touch security services
 pvt. Ltd.
 Agreement No - 31 SBD/15+16.
 Dt. of Agreement - 15/01/16
 Dt. of Completion as per
 Agreement - 14/01/18

Actual Dt. of Completion
 - 10/01/18.

Material used

① Supply, fitting & fixing

elasto-meric Bearing

& seismic Pad

$$2 \times 3 \times 14.20 \times 6 \times 9.60 = 4907.52 \text{ cu}^3$$

$$5 \times 6 \times 14.20 \times 6 \times 9.60 = 24537.60 \text{ cu}^3$$

$$= 29445.12 \text{ cu}^3$$

② P/r steel plate on

both side of elasto-
 meric seismic

$$2 \times 1 \times 0.45 \times 0.45 \times 0.05 = 0.020 \text{ m}^3$$

$$= 156.87 \text{ kg}$$

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. 10 Ponds at 100 ft x 100 ft		100	100	85.70	BF. Rs. 129666.00
2. A Binsa	10	100	100	85.70	100.00
3. 10 Ponds at 100 ft x 100 ft		100	100	85.70	100.00
4. 10 Ponds at 100 ft x 100 ft		100	100	85.70	100.00
5. 10 Ponds at 100 ft x 100 ft		100	100	85.70	100.00
6. 10 Ponds at 100 ft x 100 ft		100	100	85.70	100.00
7. 10 Ponds at 100 ft x 100 ft		100	100	85.70	100.00
8. 10 Ponds at 100 ft x 100 ft		100	100	85.70	100.00
9. 10 Ponds at 100 ft x 100 ft		100	100	85.70	100.00
10. 10 Ponds at 100 ft x 100 ft		100	100	85.70	100.00
11. Total		1000	1000	857.00	129666.00
12. C.R.P					
13. Other					
14. Total					129666.00