

4th year Maintenance

Bishnupur

6

Sch.XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	

NIW - Cons. of road from Khundgani Petrol Pump to Pakaria Bishnupur

Agency - Sri Manoj Kumar

Age No. C.R.D/04/2019-20

Actual Date of ~~Completion~~ - 25.10.2020

Date of Completion - 25.10.2020

Date of entry - 31.01.2025

15.1) Restoration of kerbs / Bemne

do cu

$$18 \times 6 \times 5 \times 0.3 = 162 \text{ m}^3$$

$$16 \times 2.8 \times 3 \times 0.3 = 40.32 \text{ m}^2$$

$$\text{total} = 202.32 \text{ m}^3$$

15.2) Making up of Bemne / shoulder

do cu

$$96 \times 4.8 \times 2.3 = 1059.84 \text{ m}^2$$

$$15 \times 3.0 \times 4.2 = 189.0 \text{ m}^2$$

$$1248.84 \text{ m}^2$$

15.3(i) Repair of Pot holes with 75mm

BM do cu

$$11 \times 4.8 \times 3.2 \times 0.075 = 12.672 \text{ m}^3$$

$$10 \times 2.5 \times 3 \times 0.075 = 5.625 \text{ m}^3$$

$$18.3 \text{ m}^3$$

15.3(ii) Patch repair over pot holes

with 20mm premix Cement

do cu

$$78 \times 1.5 \times 2.0 = 234.00 \text{ m}^2$$

$$8 \times 1.2 \times 2.1 = 20.16 \text{ m}^2$$

$$\text{total} = 254.16 \text{ m}^2$$

Continuation

## Sch.XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
7) Maintenance of C/S work 15.7.11)					
8) lab culvert	do	cu			

DTMB P - 7 = 1.00 No. 8

@ Rs. 2291.44/each = Rs. 2291.00

8) white washing of Parapet 15.7.13)	Wall of CD work				
	do	cu			

DTMB P - 7 = 103.68 m<sup>2</sup>

@ Rs. 160.17/m<sup>2</sup> = Rs. 1676.00

Total = Rs. 452,702.00

(less 0.27% below) - 1222.00

Net Payment = Rs. 451,480.00

Chk'd  
31-01-75

Material Statement