

4th year maintenance  
bill

59

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of road - Gobindpur					
Chak mazid maine					
Dessi Path chakrasaly					
Hat Sc. to Jego Bazar Baph					
Tola hitech bazar kanak chowk					
Tale					
Agoney - Ramesh vs. choudhary					
Ag. no. - 10/ SAB/mmlsy(50)/18-19					
Actual D. O. Comm - 1.04.29					
Date of measur - 5.04.23					
(1) Restoration of main cut with soil, maximum					
2 x 5 x 30.0 x 0.35 x 0.30 = 85.5 m <sup>3</sup>					(एस)
1 x 6.60 x 1.0 x 0.30 = 1.96 m <sup>3</sup>					पा. ८
					घ
(2) maintenance of earthworks					
Shoulder					
2 x 6 x 30.0 x 1.10 = 396.0					E
3 x 30 x 1.0 = 90.0					P
					T
					7:
(3) maintenance of bitumenous surface					
9 x 2 x 4.25 x 1.10 = 18.70					
9 x 2.50 x 1.25 = 12.50					
Continuation					31.20

## Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Content of area
	No.	L.	B.	D.	
(5) Patch or parts of survey filled up in plot					
50.63 m <sup>2</sup> @ 263 = 86% - 133/-					
(6) maintenance of roads					
2.08 cm (at 1024 = 49 fm - 117 =					
(7) maintenance of river &					
11) roads					
0.104 km @ 706 = 64 fm - 137					
(8) cutting of branches of trees					
6.000 m @ 200 = 1200/-					
(9) cutting of shrubs					
13.50 m @ 3 = 10.50/- 83/-					
(10) Tossing of grass					
311.25 m <sup>2</sup> @ 2 = 0.6/m <sup>2</sup> - 187.8/-					
(11) white washing two coats					
20.25 m <sup>2</sup> @ 15 = 81/m <sup>2</sup> - 320/-					
Less 10.00/- for agent					
10.989/-					
10.989/-					
3850/-					
Cumulative 511.23					
Continuation					

U.R.  
Tanjore  
15/6/14