

मोहान पुस्तकालय तालिका २०००
जगुन के उधर तक उधर नारायण

Schedule XLV Form No. 134.

Executive Engineer

Part - II

R.W.D.(W) Division

DIVISION

Darbhanga-1

MB.No. 708

Singhwa

SUB-DIVISION

Measurement Book

1226

मिस मिथुन टाडर .

3rd Year Maintenance

21

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
M/Work - Maintenance of Road					
from Dushil Paira to					
Mohampur Fakir Takiya.					
Down Buswah Kalhar Tak.					
Agency - M/S Mishra Traders					
Ag. No.	11-SB/1	19-20			
Date -	15/10/19				
Act. Coupli -	25/62/22				

Measurements.

(1) Restoration of Rain-cuts as per Specification.

3x	17.00m	x	0.95	x	0.300 =	14.54m ³
2x	13.50m	x	0.90	x	0.300 =	7.30m ³
5x	20.00m	x	0.50	x	0.300 =	15.00m ³
7x	9.00m	x	1.10	x	0.300 =	20.75m ³
2x	27.00m	x	1.10	x	0.300 =	17.82m ³
					Total =	75.41m ³
					Unit =	72.29m ³

(2) Maintenance of earthen shoulders as per Specification.

3x	2x	11.00m	x	0.75 =	49.50m ³
7x	2x	20.00m	x	0.50 =	140.00m ³
4x	2x	7.00m	x	0.95 =	53.20m ³
					242.70m ³

Continuation

3rd Year

23

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(8) cutting of shoulders = 08 Nos.					
(9) white-washing of parapets of CD walls -					
1x2x 6-20 wall x 1.60m =					19.84 m ²
1x2x 2x 0.60 wall x 0.40 =					0.96 m ²
Total =					20.80 m ²
Amer 28/2/25 AE					
Vikr 28/2/25					
<u>Abstract of Cost</u>					
(1) Restoration of Rainwater					
Vidit-1, P-21 = 72.29 m ²					
@ Rs 415.17/m ² - Rs					30013 =
(2) Repair of shoulders					
Vidit-2, P-21/22 = 401.63 m ²					
@ Rs 58.37/m ² - Rs					23443 =
(3) P/L - 75 mm B.M.					
Vidit-3, P-23 = 4.06 m ³					
@ Rs 10999.58/m ³ - Rs					44658 =
(4) Patch-repair of Pot hole					

Continuation

Continuation