

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name at work -					Maintenance
at road from Mangarh to last					
Agency -					Kambhija Lal Mahato
Agg. No -					01 / mmusy (WB) 380 / 20-21
Date at commence -					24/06/2020
Date at completion -					23/06/2021
Actual date of comp -					20/09/2021
Work done -					

① Restoration at rain cuts					
do do					all
12 X 15.50 X 1.10 X 0.30 =					61.38
10 X 10.45 X 1.35 X 0.62 =					87.46
10 X 10.15 X 1.20 X 0.35 =					42.63
4 X 10.15 X 1.20 X 0.35 =					17.052
					208.52m ³

② Making up Berms / shoulder					
do do					all
10 X 18.75 X 1.20 =					225.00
3 X 16.18 X 0.81 =					39.31
8 X 20.15 X 0.49 =					78.98
15 X 18.75 X 0.52 =					146.25
18 X 20.22 X 0.45 =					163.78

Continuation

653.32

Abstract at cost

89

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration at ruin culs					
do					all-
208.52 m ³ Page-(84) item-(1)					
₹ 379.59/m ³					79152=00
② Making up at Berms/shoulder					
do					all-
984.38 m ² Page-(85) item-(2)					
₹ 56.81/m ²					55923=00
③ Repair at pot holes filled					
do					all-
175.78 m ² Page-(85) item-(3)					
₹ 412.95/m ²					72588=00
④ Patch repair over pot holes					
do					all-
175.78 m ² Page-(86) item-(4)					
₹ 267.68/m ²					47053=00
⑤ Maintenance at Bitumen					
mix seed surfac.					do all-
175.78 m ² Page-(86) item-(5)					
₹ 285.30/m ²					50150=00
⑥ Maintenance at Hume Pipe					
culvert					do all-
3 Nos Page-(86) item-(6)					
₹ 1102.80/Each					3308=00
⑦ Maintenance at slab culvert					
do					all-

Continuation

Scanned with CamScanner