

कार्यपालक अभियन्ता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, बक्सर

पत्रांक 365 /

बक्सर, दिनांक 12/04/25 /

प्रेषक:-

कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बक्सर।

सेवा में,

नोडल पदाधिकारी,
3054 (M.R) कोषांग,
बिहार, पटना।

विषय:- शीर्ष 3054 नई अनुरक्षण नीति-2018 अंतर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक कहना है कि विहित प्रपत्र में संलग्न विवरणी के अनुसार शीर्ष Mr 3054 New Maintenance Policy-2018. अन्तर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु राशि की आवश्यकता है।

अतः कार्यहित में अनुरोध है कि उक्त अधियाचित राशि उपलब्ध कराने की कृपा की जाय ताकि कराये जा रहे कार्यों का विपत्र भुगतान किया जा सके।

- अनु०:- (1) अधियाचना प्रपत्र
(2) IRI Value Report
(3) Map
(4) प्रमाण-पत्र।


विश्वासभाजन



12.04.25

कार्यपालक अभियन्ता
ग्रा0का0वि0, कार्य प्रमण्डल,

बक्सर


12/04/25

Date-14.04.2025

Rural Works Department

[illegible]

RWD Works Division
Buxar

Executed Engineer
RWD Works Division

Om
12/04/25

12/04/2025

12/04/25
E

12/04/2025

① Prasad
12.04.25
At 720000

FORM GFR 19-A

(See Government of India's Decision (I) below Rule- 150)
Form of Utilization Certificate upto date of 13.04.2025

Name of Scheme :- MR NEW MAINTENANCE POLICY-2018.

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (Rs.In lacs)	Amount Received (Rs.In Lacs)	Particulars
		Through C.F.M.S. Received	-	
1	MR NEW MAINTENANCE POLICY-2018.	<u>BF up to 2024-2025</u> <u>Lt No-29 dt-30.03.2025</u> <u>12741.89335</u>	12741.89335	Certified that Allotment Received during the year 2024-2025 Through C.F.M.S. Rs.12741.89335 lacs of grants-in- favour of Executive Engineer, R.W.D.(W) Division, Buxar. Bihar a sum of Rs.12718.77567 lacs has been utilized for the purpose of MR NEW MAINTENANCE POLICY-2018. schemes as given in the margin for which it was sanctioned and that the balance of Rs.23.11788 lacs (allotment surrender vide Lt no-460 dt- 21.03.2025 amount Rs.17.76709) remaining unutilized at the end of the period under report.
		Total Rs. =	12741.89335	

- 2 Certified that I have satisfied myself that the conditions on which the grants- in - aid was sanctioned have been duly fulfilled. are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercise:-

- i) Works have been supervised by Executive Engineer/ Superintending Engineer
- ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- iii) Construction materials have been tested.
- iv) Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- v) All other codal formalities have been observed.

3 **Physical progress achieved:-**

- i) Construction of Road works.
- ii) Construction of CD works.


 D.A.O
 R.W.D. (W) Division.
 Buxar


 12.04.25
 Executive Engineer
 R.W.D. (W) Division.
 Buxar


 12.4.25

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर

का0आ0स..... बक्सर/ दिनांक.....


कार्यालय आदेश

प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत L048-Buxar Dhansoi Road to Bairi (L48) पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत, सहायक अभियंता द्वारा 50 प्रतिशत एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।



कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा ईटाढ़ी

सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल ईटाढ़ी



कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर


Name of Road:-L048-Buxar Dhansoi Road to Bairi (L48) Contractor Name:-Narendra Kumar

Date	Time	Section	No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	ATEGORY ROAD	Latitude	Longitude	Event	
19/3/25	13:32:0	56	0.1	230	10.1	2300	2125	G	25.50458	84.007615	Normal	$Y = 0 * X^2 + 0.816 * X + 249$ $X = 2125$ $Y = 2044$	
19/3/25	13:33:33	56	0.1	240	10.1	2400	2207	G	25.50411	84.008431	Normal		
19/3/25	13:34:14	56	0.1	220	10.1	2200	2044	G	25.50413	84.008502	Normal		
19/3/25	13:34:24	56	0.1	200	10.1	2000	1880	G	25.50408	84.009635	Normal		
19/3/25	13:35:24	56	0.1	200	10.1	2000	1880	G	25.5044	84.0115	Normal	(R) RURAL ROAD	
19/3/25	13:36:54	56	0.1	250	10.1	2500	2288	G	25.50445	84.01305	Normal	Good Average Poor	
19/3/25	13:37:29	56	0.1	200	10.1	2000	1880	G	25.50459	84.013142	Normal	<4000 4001-5000 >5001	
19/3/25	13:40:0	56	0.1	210	10.1	2100	1962	G	25.50511	84.013536	Normal		
19/3/25	13:40:25	56	0.1	210	10.1	2100	1962	G	25.50599	84.013687	Normal	IRI value=2056	
19/3/25	13:41:43	56	0.1	240	10.1	2400	2207	G	25.50638	84.013505	Normal	Machine ID=19195	
19/3/25	13:42:0	56	0.1	230	10.1	2300	2125	G	25.50657	84.013528	Normal		
19/3/25	13:43:7	56	0.1	250	10.1	2500	2288	G	25.50705	84.013591	Normal		
19/3/25	13:44:7	56	0.02	200	10.1	2000	1880	G	25.50738	84.01361	Normal		
Length				1.220									

20.3.25
20/3/25

20.3.25
EE

File: C:\Users\7SURYANAND MISHRA\Desktop\narendra\6031350.xlsx Section No. 56, Egn: test
Name of Customer: Narendra kumar, Name of Work/ Road: L048-Buxar Dhansai Road to Bairi, Lab Job number :




20.3.25
76


20.3.25
EE