कार्यपालक अभियंता का कार्यालय ग्रामीण कार्य विभाग, कार्य प्रमंडल, महुआ।

Email Id-eerwd.mahua@gmail.com

Mobile No-8986915790

पत्रांक. 677..../

महुआ / दिनांक ०५ ... / ०५ ... / 2025

प्रेषक.

ई0 अरविन्द कुमार, कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमंडल, महुआ।


सेवा में,

नोडल पदाधिकारी, एम0आर0 3054 नई अनुरक्षण नीति 2018, विश्वेश्वरैया भवन, ग्रामीण कार्य विभाग,

शीर्ष एम0आर0 3054 नई अनुरक्षण नीति 2018 अन्तर्गत पथ में कराये गए कार्य के विषय : विरुद्ध अधियाचना भेजने के संबंध में।

उपर्युक्त विषय के संबंध में कहना है कि शीर्ष एम0आर0 3054 नई अनुरक्षण नीति 2018 महाशय, अन्तर्गत पथ में कराये गए कार्य के विरूद्ध अधियाचना इस पत्र के साथ समर्पित की जा रही है।

स्कृति । प्रामीण कार्य विभाग, कार्य प्रमंडल, महुआ।



12 | 1 | 63 | N | 25 | N | 25

R.W.D, Works Division, Mahua

STATE OF THE PARTY OF THE PARTY

Form GFR 19-A

(See Government of India's Decision (1) below Rule-150) Form of Utilisation Certificate upto the month-07.04.2025

STATE- BIHAR

SL. No	Name of Scheme	Sanction No. & Date With Amount (In Rs. Lacs)	Amount Received (In Rs.Lacs)	Particulars
1	Construction of Rural Roads under MR New Maintenance Policy 2018	Lt-29 Dated- 30-03-2025 Amount- 11094.64629	400.12765	Certified that out of Rs. 11094.64629 Lacs of grants-in-aid sanctioned upto 12/2017 in favour of E-in-C , REO Bihar,Patna a sum of Rs.11046.93799 lacs has been utilized for the purpose of MR New Maintenance Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs- 47.70830 lacs remaining unutilized at the end of the period under.
-	Total:		400.12765	ditions on which the gram-in-aid was sanctioned have been

Certified that I have satisfied myself that the conditions on which the gram-in-aid was sanction 2 duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sancticed.

Kind of Checks exercised:-

- Works has been supervised by Executive Engineer/Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/Superintending Engineer. i ii
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the iii i٧ Assistant Engineer/ Executive Engineer
- All other codal formalities have been observed.
- Physical Progress achived:-
 - Construction of Road Works.
 - Construction of CD Works. ii

RWD. Works Division, Mahua