

## Sch. XLV-Form No. 134

| Particulars                        | Details of actual measurement |    |    |    | Contents of area |  |
|------------------------------------|-------------------------------|----|----|----|------------------|--|
|                                    | No.                           | L. | B. | D. |                  |  |
| 3rd year Maintenance               |                               |    |    |    |                  |  |
| from-01.03.2022 to 28.02.2023      |                               |    |    |    |                  |  |
| Name of work: Maintenance of       |                               |    |    |    |                  |  |
| road from Kaituke Nandan           |                               |    |    |    |                  |  |
| Bhumina talu to (6)                |                               |    |    |    |                  |  |
| Agency — Gopi Kumar                |                               |    |    |    |                  |  |
| Agreement No — 40.36+3.58 be       |                               |    |    |    |                  |  |
| Date of start 24/11/20             |                               |    |    |    |                  |  |
| Actual date of completion 28/02/21 |                               |    |    |    |                  |  |
| Date of measurement 28/02/21       |                               |    |    |    |                  |  |
| 1 Restoration of rain              |                               |    |    |    |                  |  |
| Cuts with Soil, mason              |                               |    |    |    |                  |  |
| a gravel —                         |                               |    |    |    |                  |  |
| 1x30 x 0.90 x 0.30 = 8.10          |                               |    |    |    |                  |  |
| 2x30 x 2 x 0.76 x 0.30 = 27.36     |                               |    |    |    |                  |  |
| 1x15 x 0.91 x 0.30 = 4.01          |                               |    |    |    |                  |  |
| 39.55m                             |                               |    |    |    |                  |  |
| 2 Maintenance of Parthen           |                               |    |    |    |                  |  |
| Shoulder by stripping              |                               |    |    |    |                  |  |
| Excess Soil from Shoulder          |                               |    |    |    |                  |  |
| 2x30 x 2 x 1.125 = 135.00          |                               |    |    |    |                  |  |
| 1x30 x 2 x 0.91 = 54.6             |                               |    |    |    |                  |  |
| 189.6                              |                               |    |    |    |                  |  |
| Total 189.6m                       |                               |    |    |    |                  |  |
| 3 Repair of Pot                    |                               |    |    |    |                  |  |
| Holes with 75mm Bm                 |                               |    |    |    |                  |  |

Continuation

| Particulars | Details of actual measurement |    |    |    | Contents of area |
|-------------|-------------------------------|----|----|----|------------------|
|             | No.                           | L. | B. | D. |                  |

Bituminous Surface  
 with 2cm Thick Premixed  
 Carpet with Seal Coat  
 Vide item Nos PN-48  
 $8N = 23.91m^2$   
 $8-351 = 62m^2$   $8402 = 45$

6 Maintenance of drain

100 Stone & K.m Stone

Vide item No 6 PN-49

$8N = 0.11cm$

$628 = 26$   $62 = 82$

7 Cutting of branches

of trees

Vide item No 5 PN-49

$8N = 1Nos$

$109 = 24$   $109 = 24$

$64942 = 24$   $64942 = 24$   $649 = 36$

Add 1% labour cost  $649 = 36$

Add 12% GST  $7792 = 40$

$73384 = 4$   $73378 = 84$

Less 11.29% below L-1  $8284 = 42$

$65099 = 4$   $65094 = 42$

say  $65090 = 4$   $65096 = 4$

Signed  
 02/03/18  
 02/3/18  
 Continuation