

कार्यपालक अभियन्ता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, बक्सर

पत्रांक 572 /

बक्सर, दिनांक 16.04.2025

प्रेषक:-

कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बक्सर।

सेवा में,

नोडल पदाधिकारी,
3054 (M.R) कोषांग,
बिहार, पटना।

विषय:- शीर्ष 3054 नई अनुरक्षण नीति-2018 अंतर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक कहना है कि विहित प्रपत्र में संलग्न विवरणी के अनुसार शीर्ष Mr 3054 New Maintenance Policy-2018. अन्तर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु राशि की आवश्यकता है।

अतः कार्यहित में अनुरोध है कि उक्त अधियाचित राशि उपलब्ध कराने की कृपा की जाय ताकि कराये जा रहे कार्यो का विपत्र भुगतान किया जा सके।

- अनु०:- (1) अधियाचना प्रपत्र
(2) IRI Value Report
(3) Map
(4) प्रमाण-पत्र।

विश्वासभाजन

(Pb)

16.04.25

कार्यपालक अभियन्ता
ग्रा०का०वि०, कार्य प्रमण्डल,

बक्सर
Om
16-04-25

FORM GFR 19-A

(See Government of India's Decision (I) below Rule- 150)
Form of Utilization Certificate upto date of 16.04.2025

Name of Scheme :- MR NEW MAINTENANCE POLICY-2018.

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (Rs.In lacs)	Amount Received (Rs.In Lacs)	Particulars
Through C.F.M.S. Received			-	
1	MR NEW MAINTENANCE POLICY 2018.	BF up to 2024-2025 Lt No-29 dt-30.03.2025 <u>12741.89335</u>	12741.89335	Certified that Allotment Received during the year 2024-2025 Throught C.F.M.S. Rs.12741.89335 lacs of grants-in- favour of Executive Engineer, R.W.D.(W) Division, Buxar. Bihar a sum of Rs.12718.77567 lacs has been utilized for the purpose of MR NEW MAINTENANCE POLICY-2018. schemes as given in the margin for which it was sanctioned and that the balance of Rs.23.11788 lacs (allotment surrender vide Lt no-460 dt- 21.03.2025 amount Rs.17.76709) remaining unutilized at the end of the period under report.
		Total Rs. =	12741.89335	

- 2 Certified that I have satisfied myself that the conditions on which the grants- in - aid was sanctioned have been duly fulfilled, are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercise:-



- Works have been supervised by Executive Engineer/ Superintending Engineer
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other codal formalities have been observed.

3 **Physical progress achieved:-**

- Construction of Road works.
- Construction of CD works.


D.A.O.

R.W.D. (W) Division,
Buxar


16.04.25
Executive Engineer
R.W.D. (W) Division,
Buxar

16.4.25

Name of Division:- RWD Works Division Buxar.

Rural Works Department
MR NEW MAINTENANCE POLICY-2018, ALLOTMENT REQUISITION

Date-16.04.2025

Sl. No.	Year	Name of Road	Name of Contractor (In English)	Project Id	Administrative Sanction		Agreement Amount (In Lacs)		Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Allotment Received (in Lacs)	Total Expenditure as per MIS (in Lacs)	Value of Measurement (in Lacs)	Current Demand (in Lacs)	Remarks
					Length (In Km)	Amount (In Lacs)	Main Work	Maintenance								
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17
148	2023-24	LOS5, SMARI SONBARSA PATH MAIN ROAD TO PANDEYPUR UPADHYAYPUR (NR65)	Narendra Kumar	10401902130	1.150	43.11700	21.79029	5.95555	2036	25	5%	0.00000	0.00100	21.79029	21.79029	Physically complete
Total=												0.00000	0.00000			

D.A.d
RWD Works Division
Buxar


16-04-25
Executive Engineer
RWD Works Division
Buxar


16-04-25


कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर

कार्यालय आदेश

प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत L065-SIMRI SONBARSA PATH MAIN ROAD TO PANDEY PUR UPADHYAYPUR (VR65) पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत, सहायक अभियंता द्वारा 50 प्रतिशत एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।


16/04/25
कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य प्रशाखा बक्सर


16/04/25
सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल बक्सर


16.04.25
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

Name of Road:-L065-SIMRI SONBARSA PATH MAIN ROAD TO PANDEYPUR UPADHYAYPUR (VR65) Contractor Name:-Narendra Kumar

Date	Time	Section	Length	Bumps	Speed	OR	IRI	ATEGORY	Latitude	Longitude	Event
15/4/25	10:02:0	No. 54	0.1	230	10.1	2300	2125	G	25.615017	84.065793	Normal
15/4/25	10:02:33	54	0.1	240	10.1	2400	2207	G	25.614769	84.066534	Normal
15/4/25	10:04:04	54	0.1	220	10.1	2200	2044	G	25.614537	84.067165	Normal
15/4/25	10:04:44	54	0.1	200	10.1	2000	1880	G	25.614337	84.067866	Normal
15/4/25	10:05:14	54	0.1	200	10.1	2000	1880	G	25.613817	84.068143	Normal
15/4/25	10:06:54	54	0.1	250	10.1	2500	2288	G	25.61311	84.067893	Normal
15/4/25	10:07:01	54	0.1	200	10.1	2000	1880	G	25.61285	84.067352	Normal
15/4/25	10:08:20	54	0.1	210	10.1	2100	1962	G	25.612578	84.06701	Normal
15/4/25	10:09:25	54	0.1	210	10.1	2100	1962	G	25.612558	84.066526	Normal
15/4/25	10:11:43	54	0.1	240	10.1	2400	2207	G	25.612563	84.06622	Normal
15/4/25	10:12:00	54	0.1	230	10.1	2300	2125	G	25.612389	84.066982	Normal
15/4/25	10:12:00	54	0.05	230	10.1	2500	1880	G	25.612212	84.065821	Normal
		length	1.150								

$$Y = 0 * X^2 + 0.816 * X + 249$$

$$X = 2125$$

$$Y = 2044$$

(R) RURAL ROAD

Good Average Poor
4001-5000 >5001

IRI value=2036

Machine ID=19195

Kanishk
16/04/25

Santhosh
16/04/25

Shubham
16/04/25

AE

Prashant
16.04.25

EE

File : C:\Users\7SURRYANAND MISHRA\Desktop\06031360.xlsx Section No. : 54, Egn : test
Name of Customer : NARENDRA KUMAR Name of Work/ Road : L065 SIMRI SONBARSA PATH MAIN ROAD TO

UV 1880 -
mm/
km



Kamlesh
16/04/25

Shr
16/04/25

Shr
16/04/25
AE

(Puls)
16-04-25
EE