

3rd Year maintenance

32

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of Road: RFO Sadak					
Bhushan Phakur ke charho					
Rampur mani Uttar Tak					
2. Name of Agency: Nandkishor					
THAKUR					
3. Agreement no: 34/SRD/2020-21					
4. Actual date of completion: 15.05.2022					
work done					
① Restoration of rain cuts					
with soil - duff					
3 x 20.50 x 1.20 x 0.30 = 22.14					
4 x 20.60 x 1.00 x 0.32 = 26.368					
3 x 20.60 x 0.89 x 0.28 = 15.400					
4 x 20.60 x 1.00 x 0.30 = 24.72					
3 x 20.00 x 0.80 x 0.30 = 14.40					
1 x 2.50 x 0.80 x 0.28 = 0.560					
Qty = 103.588m ³					
Say 103.48m ³					
② 1/2 maintenance of earthen					
shoulder - duff					
3 x 20.60 x 1.20 = 74.16					
4 x 20.80 x 1.00 = 83.20					
8 x 30.00 x 0.85 = 204.0					
8 x 30.00 x 0.86 = 206.40					
2 x 7.12 x 0.50 = 7.12					
Qty = 574.88m ²					
③ Repair to post holes m/s					

Continuation

P.T.O.

Continuation