

Item Maintenance

34
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
name of work-	811 ramp up to Ramp				
Agency-	Sanyal Karm				
Appd -	45.11.15 / 16/2015				
Actual dt. of comp -	02/06/2015				

(1) Restoration of pavin

Culvert

10x 5.00x 1.00x .300 =	15.00 m ³
8x 4.00x .900x .300 =	8.64 m ³
9x 5.00x .700x .300 =	5.67 m ³
8x 7.00x .500x .300 =	8.40 m ³
9x 10.00x .400x .300 =	10.80 m ³
07x 10.00x .400x .280 =	9.00 m ³
	= 57.51 m ³

(2) Maintenance of earth -

Shoulder do

8x 10.00x 1.00 =	80.00 m ³
10x 12.00x .900 =	108.00 m ³
9x 8.00x .400 =	28.80 m ³
01x 20.00x 1.00 =	20.00 m ³
9x 11.00x .700 =	69.30 m ³
	= 325.90 m ³

(3) Maintenance of kerb p/e

Culvert

= 03.92

Continuation

Continuation

Road Maintenance

37

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Along of work - Bitarapur to Ranpur.					
Agan of -					
Agan of -					
Agan of -					
Agan of -					

(1) Destruction of Rain Cut

9x10.00x.400x.250 =	9.00 m ³
8x7.00x.500x.300 =	8.40 m ³
9x10.00x.700x.300 =	10.80 m ³
10x5.00x.1.00x.300 =	15.00 m ³
8x9.00x.500x.300 =	8.40 m ³
9x5.00x.700x.300 =	5.67 m ³
10x11.00x.1.200x.300 =	6.60 m ³
8x5.00x.700x.300 =	4.80 m ³
1x12.00x.600x.800 =	2.16 m ³
	= 71.07 m ³

(2) Mairala of earth

Shoulder - do do	
8x9.00x.1.000 =	72.00 m ³
8x10.00x.1.000 =	80.00 m ³
10x12.00x.900 =	108.00 m ³
01x20.00x.1.000 =	20.00 m ³
9x11.00x.800 =	79.20 m ³
	= 359.20 m ³

Continuation



Continuation

