

5th year Maintenance Bill.

84

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w - Construction and Maintenance of Road from Tarabari Mahespur Purabhetta via Karari Kanarsdang in Thokurpanj Block					
Agency:- M/s ability Construction					
Aggno:- 79/NARAR/SRD/18-19					
Date of receipt - 15/11/19					
Measurement Record					

1) Restoration of Rain cuts					
	3	20	7.25	0.3	22.50
	2	15.0	0.90	0.3	8.10
	1	22.0	1.25	0.3	8.25
	8	20.0	0.70	0.3	43.20
	2	28.0	1.25	0.3	21.00
	6	25	1.25	0.30	56.25
	10	30	0.90	0.3	81.00
	2	28	1.25	0.3	21.00
					261.30
					m ³
2) Maintenance of earthen shoulder					
	5	15.0	1.00		75.00

Continuation

Abstract of cost-

1) Restoration of
dams cuts

$$Qty = 261.30 \text{ m}^2 \text{ vide p. 84}$$

$$① 378.70/\text{m}^2 - R - 98954 = W$$

2) Maintenance of
earthen shoulder

$$Qty = 1517.0 \text{ m}^2 \text{ vide p. 85}$$

$$① 56.85/\text{m}^2 - R - 86241 = W$$

3) Maintenance of
worn road

$$Qty = 237.88 \text{ m}^2 \text{ vide p. 85}$$

$$① 226.06/\text{m}^2 - R - 53725 = W$$

4) patch repairs over
POT by MTS

$$Qty = 237.88 \text{ m}^2 \text{ vide p. 85}$$

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	↓	B.	D.	
①	2.20/m ²		B		756324
12) White washing of					
f. walls					
Qty = 56.25 m ²					
Wedge - 87					
②	21.81/m ²		B		122724
2204 B - 356017					
10% below - 356022					
B - 320452					
10% below - 356022					
9/8/24					

Material Statement

①	Soil	488.85 m ³
②	Stone chips	335.41 m ³
③	Bitumen	580.42 kg