

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/Inlook	Mamshiwana Khatanga				
	to Reburu Rakeri.				
Agency	M/S R.K Const & Co.				
	At- Bailly Road Near-				
	Saguna more, Patna.				
Agreement No	42/SBD/ MMWSY/19-20				
Date at Start	10.08.2019				
Date at Actual completion	13.10.20				
Date at measurement					
	Inlook done				
(1) Restoration at Raincuts					
do - do					
	16 x 6.50 x	1.20 x	0.3	=	37.44
	5 x 8.90 x	1.10 x	0.3	=	14.69
	10 x 10.50 x	1.20 x	0.3	=	37.80
	14 x 15.10 x	1.10 x	0.3	=	69.76
	10 x 5.50 x	1.0 x	0.3	=	16.50
	8 x 4.80 x	1.20 x	0.3	=	13.82
	6 x 2.50 x	1.0 x	0.3	=	4.50
	U- 195.78 m ²				194.51
(2) making up at Bump					
Shoulder stripping do - do					
	15 x 9.80 x	1.0		=	147.0
	10 x 6.80 x	1.20		=	81.60
	16 x 11.80 x	1.0		=	188.80
	18 x 15.50 x	1.10		=	306.90
	11 x 12.10 x	1.20		=	159.72

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration at Fly cuts					
do - do -					
	Qty	vide	TMB		
Page No -	50	=	192.78 m ²		
@ ₹ 415.17/m ²				₹	80037.0
(2) Making up the Berm					
do - do -					
	Qty	vide	TMB		
Page No -	50	=	1071.0 m ²		
@ ₹ 58.37/m ²				₹	62514.0
(3) Repair ab pot holes					
Filled with 75 mm de					
	Qty	vide	TMB		
Page No -	51	=	14.34 m ²		
@ ₹ 9897.58/m ²				₹	141931.0
(4) Patch repairs over pot holes do - do -					
	Qty	vide	TMB		
Page No -	51	=	191.25 m ²		
@ ₹ 250.78/m ²				₹	47962.0
(5) main drainage ab 40 works					
do - do -					
	Qty	vide	TMB		
Page No -	51	=	3205		
@ ₹ 1117.01/0.005				₹	3351.0
(6) cutting ab branches ab					
trees do - do -					
	Qty	vide	TMB		

Continuation

Continuation