

MM 445 Y-5T

MB. No - 72
year - 2018-19

Schedule XLV-Form No. 134

To L to Mandad Talu

DIVISION

SUB-DIVISION

Mingajer Karmat Taluqar

Measurement Book

Block - Badger's 10th

4th year Maintenance

61
Sch. XLV-Form No. 134 Abstract of cost

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: Maint of Rd from Tol to Mandol Tol.					
Agency - Niranjan Kumar Thakur.					
Agreement No — 355B/D/2018-19					
Dated Commencement — 05/03/19					
Actual Date of Completion 28/04/20					
① Restoration of drain cuts/berms with soil, medium.					
40.44 m ² @ V.T.H.B.P. 5751/14					
@ Rs. 365.25/m ² Rs. 14772.00					
② Making up of berms/shoulder stripping excess soil, from the shoulder					
314.70 m ² @ V.T.H.B.P. 5751/14					
@ Rs. 54.16/m ² Rs. 17044.00					
③ Repair of potholes filled with 7.5 mm coarse					
46.80 m ² @ V.T.H.B.P. 5851-3/3					
@ Rs. 355.45/m ² Rs. 16635.00					
④ Patch repair of bituminous surface with 20 mm Mix Seal Surfacing.					
46.80 m ² @ V.T.H.B.P. 5951/15					
@ Rs. 216.18/m ² Rs. 10117.00					
⑤ Maintenance of 12 P.C. Culvert					
2.00 Nos @ V.T.H.B.P. 5951-2/2					
@ Rs. 1131.64/each Rs. 2263.00					
⑥ Maintenance of Road Sign					

1.00 Nos. C.V. T.M.B.P. 59.31/11/11

@ Rs. 107.48/each Rs 107.00

(9) Cutting of chacks from Roadway.

5.00 Nos. C.V. T.M.B.P. 60.81/11/11

@ Rs 6.60/each Rs 33.00

(10) 9 nos of covered

2.93 m² C.V. T.M.B.P. 60.81/11/11

@ Rs 2.20/m² Rs 6.00

(11) White washing of parapet wall of CD work.

41.60 m² C.V. T.M.B.P. 60.81/12

@ Rs. 16.48/m² Rs. 686.00

Total Rs. 61,859.00

Less 10% Below Rs. 6186.00

Payable Rs. 55,673.00

M 25/4/24
7C

Sy. 25/4/24
AS

6/10/11/24

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5th Year Maintenance					
Name of work - Construction & Maintenance					
of Road from Tola to					
Mandal-tola					
Name of Agency - Nilganga Nagar Palika					
Agreement No - 3533/2018-2019					
Work order - 5/03/2019					
Actual date of Completion - 28/04/2020					
Report Entry					
Date of Entry -					
1/ Restoration of pavements					
with soil mixture					
1x	28.39x	1.35x	0.35=	13.37m ³	

1x	6.95x	1.72x	0.76=	9.08	"
1x	2.70x	1.81x	0.65=	3.17	"
				Total 40.32m ³	

2/2	Maintenance of earthwork				
	Shoulder Making up				
1x	12.45x	1.57=	19.54m ²		
8x	5.25x	1.65=	69.30 "		
4x	7.10x	1.72=	48.84 "		
1x	16.55x	1.59=	26.31 "		
1x	17.45x	1.67=	29.14 "		
1x	18.20x	1.73=	31.48 "		
1x	21.10x	1.63=	34.39 "		
5x	6.65x	1.70=	56.52 "		
C/o				Total 315.52m ²	

1.91443