

MILKSY NEW SC

1st 13. NO. 3307

ଶ୍ରୀମତୀ ସିତାମାଳାଙ୍କୁ ଆପଣଙ୍କୁ ଶୁଭାଶୀର୍ବାଦ ପଠାଉଛୁ।
ଶ୍ରୀମତୀଙ୍କ ନାମରେ ଶେଡୁଲ୍ XLV Form No. 134.

ପଞ୍ଜାବୀ/ସି/ସି/ସି

DIVISION

ପଞ୍ଜାବୀ/ସି/ସି/ସି

SUB-DIVISION

ପଞ୍ଜାବୀ

Measurement Book

1st 13. NO. 3307

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W - Chabara Suran path to Akhrami Dusadh. Hala ke Ramjan Rai ke ghartak.					
Agency - Shambhu Singh					
Agreement NO - 76550/20-21					
Work started - 6/3/20					
A.D.C. - 21/3/22					
① Restoration of drain cut.					
$7 \times 3.88 \times 1.10 \times 0.300 = 8.96 M^3$					
$7 \times 3.95 \times 1.15 \times 0.300 = 9.54 "$					
$9 \times 3.90 \times 1.20 \times 0.300 = 12.64 "$					
$5 \times 3.60 \times 1.15 \times 0.300 = 9.24 "$					
$2 \times 5.85 \times 1.22 \times 0.300 = 14.98 "$					
$7 \times 4.15 \times 1.20 \times 0.300 = 10.46 "$					
$6 \times 4.80 \times 1.25 \times 0.300 = 10.80$					
$1 \times 5.20 \times 1.25 \times 0.300 = 2.160$					
$7 \times 7.13 \times 1.25 \times 0.300 = 18.72$					
					116.94 M ³
② Making up shoulder.					
$29 \times 13.58 \times 1.25 = 492.19 M^2$					
③ Patch repair over pothole with 20mm carpet.					
$10 \times 7.03 \times 1.25 = 87.89 M^2$					
④ Patch repair over bituminous surface at same as first time NO - ③ 87.89 M ²					
⑤ Maintenance of column pipe culvert - 3 NO					
⑥ Maintenance of 15' slab culvert 1 NO.					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑦ Maintenance of road					
Segn. 0.250 Km					
⑧ Maintenance of 200 M &					
Km slope. 0.300 Km					
⑨ Cutting of branches of					
tree — 3 NO.					
⑩ Cutting of shrubs — 13 NO					
⑪ Training of grass — 32 M ²					
⑫ Road marking —					
40x20x0.100 = 80 M ²					
⑬ Road marking in BT					
portion — 100x25x0.100 = 250 M ²					
⑭ White washing — 63 M ²					
⑮ Maintenance of planted					
tree — 126 NO.					
<i>[Signature]</i>					
26/3/15					
JTE					
<i>[Signature]</i>					
26/3/15					
AB					

Abstract of cost

83

Sch. XLV-Form No. 134

Particulars	Details of actual measurement			Contents of area
	No.	B.	D.	
① Restoration of rain cuts.				
QVTRP - (81)	116.94 M ³			
CR 386.14 / M ³				R ₀ 45157=00
② Making up shoulder.				
QVTRP - (81)	492.19 M ²			
CR 57.36 / M ²				R ₀ 28232=00
③ Patch repair over pothole				
QVTRP - (81)	87.89 M ²			
CR 281.18 / M ²				R ₀ 24713=00
④ Patch repair over bitumin surface.				
QVTRP - (81)	87.89 M ²			
CR 299.36 / M ²				R ₀ 26311=00
⑤ Maintenance of CD				
Time rate - QVTRP - (81)				
3 No CR 1130.67 each				R ₀ 3392=00
⑥ Maintenance of CD slope				
Cutwork - QVTRP - (81)				
1 No CR 2329.20 each				R ₀ 2329=00
⑦ Maintenance of road				
Segu - QVTRP - (82)				
0.25 km CR 1077.82 / km				R ₀ 267=00
⑧ Maintenance of 200 M ²				
km slope - QVTRP - (82)				
0.300 km CR 109.74 / km				R ₀ 187=00
⑨ Cutting of branches of trees.				
QVTRP - (82)				
3 No CR 109.74 each				R ₀ 329=00

Continuation

Continuation