

Maintenace MB MEASUREMENT

Schedule XLV Form N.134.

P.W.D.

1985

Chudde noahs 1/2 a la Se
CHOSPUK (Narvik)

~~BARHAT~~

SUB DIVISION

Prav ear kg Passun

MEASUREMENT BOOK

4th year Maintenance bill

Sch. XLV- Form No. 134

28

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
1/10 Chandrabani to/a					
Chaspur in sandika south					
porchgate to Mohanpur					
pm 654 Recd.					
Agency- provin Kurnor prach					
Agreement no- 97 SBD 19-20					
Actual date of completion- 24-12-2020					
1) Restoration of ruin Cutt.					
do do all Comp					
$15 \times 6 \text{ m} \times 1.50 \text{ m} \times 0.30 \text{ m} =$					40.50 m^3
$10 \times 3 \text{ m} \times 1.30 \text{ m} \times 0.30 \text{ m} =$					11.70 m^3
$10 \times 4 \text{ m} \times 1.20 \text{ m} \times 0.30 \text{ m} =$					14.40 m^3
					96.84 m^3
2) Making up of Berms/shoulder.					
do do all Comp					
$2 \times 30 \text{ m} \times 8 \times 1.00 =$					480.00 m^2
$1 \times 20 \text{ m} \times 1 \times 1.00 =$					20.00 m^2
$1 \times 30 \text{ m} \times 1 \times 1.00 =$					30.00 m^2
$1 \times 20 \text{ m} \times 1 \times 1.00 =$					20.00 m^2
					550.00 m^2
3) Repair of pot - holes.					
do do all Comp					
$5 \times 4 \times 0.90 \times 0.075 \text{ m} =$					1.35 m^3
$10 \times 5 \times 1.00 \times 0.075 \text{ m} =$					3.75 m^3
					5.10 m^3

(Continuation)

