

WIMBLESY

SL

आयमनवाट

Const of Road & CD WORK FROM Pmmsy Harlaht
to reach Khairam.

Schedule XLV-Form No.-134

Agreement NO- 119/SBD/2019-20.

Agreement Value - 1,34,52,897 = W **DIVISION**

SUB-DIVISION

$$\begin{array}{r} 441 \\ \hline 30519 \end{array}$$

MEASUREMENT BOOK

R.K. CONSTRUCTION.

3rd year Maintenance

41

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Repair of Potholes filled with WBM with					
	5	1.2	.90	M ²	5.40
	3	1.5	1.2	M ²	5.40
	1	4	1.5	M ²	6.0
	2	3	1.2	M ²	7.20
	4	1.1	.85	M ²	3.74
	3	1.3	.80	M ²	3.12
	6	.90	.90	M ²	4.86
	2	2.5	1.12	M ²	5.60
	4	1.0	.70	M ²	2.80
	7	.95	.75	M ²	4.98
	6	2.5	1.2	M ²	18
	3	1.1	.60	M ²	1.98
	5	.90	.80	M ²	3.60
	1	3	1.5	M ²	4.50
	7	.80	.60	M ²	3.36
	4	1.05	.75	M ²	3.15
	2	3	1.3	M ²	7.80
	6	1.15	.65	M ²	4.48
	7	2	1.1	M ²	2.20
	3	.90	.70	M ²	1.89
	2	2	1.12	M ²	4.48
	3	.80	.85	M ²	2.04
	5	.85	.75	M ²	3.18
	3	1.5	1.0	M ²	4.50
	2	2	1.0	M ²	4.0
				Total	119.26

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(2) Repair of Potholes					
20mm Primex Carpet					
5 x .90 x .95	m ²	4.27			
4 x 1.1 x .80	m ²	3.52			
1 x 3.5 x 1.3	m ²	4.55			
2 x 2.2 x 1.0	m ²	4.40			
3 x .80 x .85	m ²	2.54			
5 x .85 x .90	m ²	3.82			
7 x .70 x .75	m ²	3.67			
4 x 1.2 x 1.1	m ²	5.28			
5 x .80 x .85	m ²	3.40			
2 x 1.9 x 1.2	m ²	4.56			
1 x 3 x 1.5	m ²	4.50			
4 x 1.5 x 1.3	m ²	7.8			
6 x .90 x .70	m ²	3.78			
4 x .80 x .85	m ²	2.72			
3 x 1.2 x 1.0	m ²	3.60			
8 x .80 x .70	m ²	4.48			
7 x .95 x .80	m ²	5.32			
5 x .85 x .90	m ²	3.82			
2 x 2.4 x 1.2	m ²	5.76			
1 x 3.5 x 1.5	m ²	5.25			
6 x .80 x .50	m ²	2.40			
9 x .70 x .60	m ²	3.78			
3 x .90 x .85	m ²	2.29			
2 x 2 x 1.5	m ²	6.0			
15 x .90 x .85	m ²	10.8			
8 x .80 x .70	m ²	4.48			
1 x 2.21 x 1.0	m ²	2.21			
Total					118.50 m ²

Continuation

Continuation

ABSTRACT

44

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of main cuts P-39/1					
148.34 M ³ @ 378.32 / M ³					56120
② Maintenance of earthen shoulder P-40/2					
573.52 M ² @ 58.18 / M ²					33367
③ Repair of Potholes filled WBM with P-41/1					
119.26 M ² @ 408.99 / M ²					48776
④ Repair of Potholes 20 mm Primer Carpet P-42/2					
118.50 M ² @ 306.49 / M ²					3631.9
⑤ Repair of Potholes 20 mm M.S.S P-43/3					
119.26 M ² @ 240.89 / M ²					28729
⑥ Maintenance of Hume Pipe P-43/4					
3 Nos @ 1109.67 / ea					3329
⑦ Maintenance of Slab culvert P-43/5					
1 No @ 2291.44 / m ²					2291

Continuation

2,08,931

Continuation