

NYSDOT Form 1466 / 2020 - 2021

Schedule XLV-Form No. 134

LOGS of NON EM (181-M-NS-4) (SIC)

STAY - STAYOR ACCELERATED

DIVISION

ET 2011

SUB-DIVISION

MEASUREMENT BOOK

FILE - No STAYOR ACCELERATED

Particulars	Limits of actual measurement				Contents of area
	No	T	B	D	
2nd year main frame					
Name of work: Work to					
dama dala					
Authority: P.P. R.W.D.					
Dalsinghgarh					
Agency: M/S. Brijwadi					
Construction					
D/S: 25/06/2020					
D/C: 24/06/2021					
M/D: 08/07/2021					
Date of entry: 08/07/2022					
Work Done					

① P.H. Restoration of
Rain Cuts ————

$$2.4 \text{ Nos } 2 \text{ sides } 2.100 \times 1.25 \times 0.300$$

$$= 53.55$$

m^3

$$1 \text{ No } 2 \text{ sides } 1.45 \times 1.00 \times 0.300$$

$$= 0.87 \text{ m}^3$$

$$\underline{54.42 \text{ m}^3}$$

② P.H. excess of
Soil ————

$$2.2 \text{ Nos } 2 \text{ sides } 2.100 \times 1.25 = 325.50 \text{ m}^2$$

$$1 \text{ No } 2 \text{ sides } 1.15 \times 0.900 = 2.07 \text{ m}^2$$

$$\underline{327.57 \text{ m}^2}$$

Particulars	Twelve of initial measurement			Twelve of final
	No.	1	2	
③ MV maintenance of Culvert - 20 - 20 W ^m				
④ MV maintenance of Planting Area - 20 - 20 W ^m				

ABSTRACT of COST

Date of Entry: 08/06/2023

① MV Restoration of Perimeter

Qty vide TMS Page

No. (33) Item No. ①

- 54142 m³

@ 386.14/m³ = 21014.00

② MV Access of Soil - 50

Qty vide TMS Page

No. (33) Item No. ②

- 327.52 m²

@ 57.36/m² = 18789.00

Continuation

Co. 39803.00

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
③ Plv maintenance of 40 S.					
Qty vide TMS Page No 40 Item 3					
- 2 ASB					
① 1130.67/each					
					2261.00
④ Plv maintenance of already planted tree 5M					
Qty vide TMS Page No 40 Item 4					
- 20 MS					
① 670.94/each					
					13419.00
					55483.00
Add 10% L.S.T. =					6658.00
Add 1% Labour cess =					555.00
					62636.00
Deduct 0.5% C.S. for Agreement					
() =					207.00
					62489.00

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No	L	B	D.	
3rd	Year				Main formula
Name of work					Loss to formula to be
Authority					EE R.W.D. Darsing 49000
Agency					M/S Bhagwati Construction
S/S		25/06/2020			
S/C		29/08/2021			
ALD/C		08/06/2021			
Date of survey		23/05/2024			Work done
①	PIV Restoration of				
	Rain Guts				50
	4 No x 2 side x 2.100 x 1.25 x 0.300				63.00 m ²
	1 No x 2 side x 1.00' x 0.85 x 0.300				0.51 m ²
					63.51 m ²
	as per limit				63.50 m ²
②	PIV excess of				
	Soil				50
	62 No x 2 side x 2.100 x 1.25 = 325.50				m ²
	1 No x 2 side x 1.15 x 0.900 = 2.07 m ²				
					327.57 m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No	L	B	D	
ABSTRACT of work					
Date of entry					23/06/2024
① Pl. Restoration of rainlets — SM					
Qty vide TMS Page No					
(42) Item no. ①					
					62.50 m ³
					② 386.14/m ³
					= 2452000
② Pl. excess of soil — SM					
Qty vide TMS Page No					
No. (42) Item no. ②					
					322.57 m ²
					② 57.31/m ² = 1878900
③ Pl. Repair of Pot holes — SM B.M. In					
Qty vide TMS Page No					
No. (43) Item no. ③					
					1.05 m ³
					② 10743.82/m ³ = 11281000
④ Pl. Patch Repair over B.M. — SM					
Qty vide TMS Page No					
No. (43) Item no. ④					
					14.00 m ²
					② 258.39/m ² = 3617000

Continuation

G. 5820700

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
5) P/W maintenance of C/D - Su					
Qty vide TMB Page					
No. (43) Item no. (3)					
- 2 No					
(2) 1120.67/each					
					= 2261.34
6) P/W maintenance of already Planke area - Su					
Qty vide TMB Page					
No. (43) Item no. (6)					
- 20 No					
(2) 574.05/each					
					= 11481.00
7) P/W Road marking					
8) Pice Partition					
Qty vide TMB Page					
No. (43) Item no. (1)					
- 139.25 m ²					
(2) 735.44/m ²					
					= 102373.00
ii) B.T Partition					
Qty vide TMB Page No. (43)					
Item no. (7) (ii) - 40.00 m ²					
(2) 735.44/m ² & 29498.00					

Continuation

C. 203740.00

